

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 7/25/2017
NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1729154789

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company: Chevron <i>4323</i>	Contact: Josepha DeLeon	
Address: 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: office: 575-263-0424; cell: 432-425-1528	
Facility Name: Skelly Unit #952	Facility Type: Injection Well	
Surface Owner: BLM	Mineral Owner:	API No.: 30-015-32895


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	17S	31E	990'	North	990'	West	Eddy

Latitude 32° 49' 28.06" N Longitude 103° 52' 46.29" W

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 0.03 barrels produced water	Volume Recovered: 0 barrels
Source of Release: Injection Flow Line	Date and Hour of Occurrence: 7/10/2017; 12:00 PM	Date and Hour of Discovery: 7/10/2017; 02:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A leak from injection flow line. The well was shut in to stop the leak and repair the flow line. The calculated volume of the release is below the reportable threshold defined in 19.15.29.7 NMAC – Rp.19.15.3.116 NMAC, 12/1/08.; the form is submitted at the request of the NMOCD.		
Describe Area Affected and Cleanup Action Taken.* The spill is to land outside of fenced well head.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

		OIL CONSERVATION DIVISION	
Signature:		Approved by Environmental Specialist:	
Printed Name: Josepha DeLeon		<i>Accepted for Record MB</i>	
Title: Environmental Compliance Specialist		Approval Date: <i>10/18/17</i>	Expiration Date: <i>N/A</i>
E-mail Address: jdx@chevron.com		Conditions of Approval:	
Date: 07/24/2017 Phone: 432-425-1528		Attached <input type="checkbox"/> <i>2RP-4445</i>	

* Attach Additional Sheets If Necessary

NOTE: Late entry for this C-141 per MBratcher. Release volume may be subject to revision based on delineation results. MB 10/18/17