District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NM OIL CONSERVATION ARTESIA DISTRICT

OCT 2 4 2017

Form C-141 Revised April 3, 2017

Submit 1 Copy to appropriate District Office in **RECEIVED** dance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1729847986	DERID#613	7 OPERATOR	Initial Report	Final Report
Name of Company Devon Energy Production Company		Contact Michael Shoemaker, EHS Professional		
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 575-513-5035		
Facility Name Harroun Trust 31 Fed Com 1		Facility Type Gas		
Surface Owner Private Mineral Owner		State	API No. 30-015-2	26954

LOCATION OF RELEASE Unit Letter Section Township Feet from the North/South Line Feet from the East/West Line County Range L 31 23S 29E 1980' FSL 660' FWL Eddy

Latitude 32.2597504 Longitude -104.0301666 NAD83

NATURE OF RELEASE Type of Release Volume of Release Volume Recovered N/A N/A N/A Source of Release Date and Hour of Occurrence Date and Hour of Discovery 3rd Party Trespass Tank Fire October 10, 2017 @ October 10, 2017 @ approximately 6 PM approximately 6 PM Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No 🛛 Not Required N/A By Whom? Date and Hour N/A N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. 🗌 Yes 🛛 No N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* This was a Trespassing incident that occurred on a Devon Energy leasehold. Multiple tanks were placed at the request of a pipeline installation company performing work for a pipeline company this work is not related to any Devon operations in this area. Devon did not order the tanks nor were we contacted and asked permission to have the tanks placed on our location. Devon was only made aware of the fire that occurred because we were contacted by the fire department who extinguished the fire which occurred on the tanks which were set by the 3rd party contractor. Describe Area Affected and Cleanup Action Taken.* After reviewing this incident with OCD, Devon is submitting this in cooperation with OCD to allow a path for this incident to be closed. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. **OIL CONSERVATION DIVISION** Signature: Sheila Fisher Approved by Environment & Spectral stree Branches Printed Name: Sheila Fisher **Expiration Date:** Title: Field Admin Support Approval Date: E-mail Address: Sheila.Fisher@dvn.com Conditions of Approval Attached -INAL Date: 10/16/17 Phone: 575.748.1829

* Attach Additional Sheets If Necessary