Office District I			
	Energy, Minerals and Nat	tural Resources	Revised November 3, 201
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II 811 S. First SHOBBS2OCD District III	OIL CONSERVATIO	N DIVISION	30-0 1 5-23202
	1220 South St. Fra		5. Indicate Type of Lease STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8		6. State Oil & Gas Lease No.
220 S. St. Francis Dr., Santa Fe, NM	Sumu 1 9, 1414 (0. State On & Cas Lease NO.
	ES AND REPORTS ON WELL	<u> </u>	
READER FOR BODOS	LES AND REPORTS ON WELL	.S LUG BACK TO A	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		STATE IC	
ROPOSALS.)			8. Well Number 1
. Type of Well: Oil Well	Gas Well Other		
2. Name of Operator CHEVRON USA INC		9. OGRID Number 4323	
. Address of Operator			10. Pool name or Wildcat
	HOBBS, NM 88240		UPPER PENN
. Well Location			
	from the <u>NORTH</u> line and <u>1980</u>	feet from the WES'	T line
			<u>1 1110</u>
Section <u>7</u> Township <u>2</u>	<u>4S Range 25E NMPM</u>	County EDDY	
	11. Elevation <i>(Show whether Di</i> 4022' GL	к, ККВ, КІ, GR, etc	
Check Appropriate Desta		Depart or Other I	Data
. Check Appropriate Box to	multate mature of motice, f	report of Other I	Jala
NOTICE OF INT	ENTION TO:	SUE	SEQUENT REPORT OF:
		REMEDIAL WOR	
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	
ULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	ІТ ЈОВ 🔲
	_		
THER:			ready for OCD inspection after P&A
			erator's pit permit and closure plan. properly abandoned.
 Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAR 	ed and leveled. Cathodic protect eter and at least 4' above ground SE NAME, WELL NUMBER,	tion holes have been l level has been set i API NUMBER, Q	n properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR
 Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAT UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as ther production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r CD rules and the terms of the Opera om lease and well location. All metal bolts and other materials be removed.) All other environmental concerns Pipelines and flow lines have beet trieved flow lines and pipelines. 	ed and leveled. Cathodic protect eter and at least 4' above ground SE NAME, WELL NUMBER, , TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUF nearly as possible to original gro d risers have been cut off at least emaining well on lease, the batte tor's pit permit and closure plan. s have been removed. Portable b s have been addressed as per OC n abandoned in accordance with emaining well on lease: all electro on infrastructure.	tion holes have been il level has been set i <u>API NUMBER, OF</u> <u>All INFORMATE</u> und contour and has t two feet below gro ery and pit location(s All flow lines, proc bases have been remo D rules. 19.15.35.10 NMAC	a properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- nd lines have been removed from lease and we
Rat hole and cellar have been fill A steel marker at least 4" in diam <u>OPERATOR NAME, LEAN</u> <u>UNIT LETTER, SECTION</u> <u>PERMANENTLY STAMP</u> The location has been leveled as the production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r CD rules and the terms of the Opera om lease and well location. All metal bolts and other materials be removed.) All other environmental concerns Pipelines and flow lines have bee trieved flow lines and pipelines. If this is a one-well lease or last r cation, except for utility's distribution hen all work has been completed, re	ed and leveled. Cathodic protect eter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUF nearly as possible to original gro d risers have been cut off at least emaining well on lease, the batte tor's pit permit and closure plan. s have been removed. Portable b s have been addressed as per OC n abandoned in accordance with emaining well on lease: all electron infrastructure. turn this form to the appropriate	tion holes have been 1 level has been set i API NUMBER, QU All INFORMATI RFACE. und contour and has t two feet below gro ery and pit location(s All flow lines, pro- pases have been remo D rules. 19.15.35.10 NMAC rical service poles ar District office to scl	 a properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been remove oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- nd lines have been removed from lease and we hedule an inspection.
 Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAT UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as the production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r CD rules and the terms of the Opera om lease and well location. All metal bolts and other materials be removed.) All other environmental concerns Pipelines and flow lines have beet trieved flow lines and pipelines. If this is a one-well lease or last r cation, except for utility's distribution hen all work has been completed, removed. 	ed and leveled. Cathodic protect eter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUF nearly as possible to original gro d risers have been cut off at least emaining well on lease, the batte tor's pit permit and closure plan. s have been removed. Portable b s have been addressed as per OC n abandoned in accordance with emaining well on lease: all electron infrastructure. turn this form to the appropriate	tion holes have been 1 level has been set i API NUMBER, QU All INFORMATI RFACE. und contour and has t two feet below gro ery and pit location(s All flow lines, pro- pases have been remo D rules. 19.15.35.10 NMAC rical service poles ar District office to scl	a properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- nd lines have been removed from lease and we
Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEA UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as the production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r CD rules and the terms of the Opera om lease and well location. All metal bolts and other materials be removed.) All other environmental concerns Pipelines and flow lines have bee trieved flow lines and pipelines. If this is a one-well lease or last r cation, except for utility's distribution hen all work has been completed, re GNATURE (PE OR PRINT NAME <u>CINDY HE</u>	ed and leveled. Cathodic protect eter and at least 4' above ground SE NAME, WELL NUMBER, , TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUF nearly as possible to original gro d risers have been cut off at least emaining well on lease, the batter tor's pit permit and closure plan. Is have been removed. Portable b is have been addressed as per OC n abandoned in accordance with emaining well on lease: all electron infrastructure. turn this form to the appropriate Muub	tion holes have been a level has been set i API NUMBER, OF All INFORMATI RFACE. und contour and has t two feet below gro ery and pit location(s All flow lines, pro- bases have been remo- bases have	 a properly abandoned. n concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been remove oved. (Poured onsite concrete bases do not have c. All fluids have been removed from non- nd lines have been removed from lease and we hedule an inspection.
 Rat hole and cellar have been fill A steel marker at least 4" in diam OPERATOR NAME, LEAN UNIT LETTER, SECTION PERMANENTLY STAMP The location has been leveled as the production equipment. Anchors, dead men, tie downs an If this is a one-well lease or last r CD rules and the terms of the Opera om lease and well location. All metal bolts and other materials be removed.) All other environmental concerns Pipelines and flow lines have been trieved flow lines and pipelines. If this is a one-well lease or last r cation, except for utility's distribution hen all work has been completed, reference. 	ed and leveled. Cathodic protect eter and at least 4' above ground SE NAME, WELL NUMBER, , TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUF nearly as possible to original gro d risers have been cut off at least emaining well on lease, the batte tor's pit permit and closure plan. Is have been removed. Portable b is have been addressed as per OC n abandoned in accordance with emaining well on lease: all electron infrastructure. turn this form to the appropriate Muub	tion holes have been a level has been set i API NUMBER, QU All INFORMATI RFACE. und contour and has t two feet below gro bry and pit location(s All flow lines, pro- bases have been remo D rules. 19.15.35.10 NMAC rical service poles ar District office to scl PERMITTING SPE- _EEOF@CHEVRC	A properly abandoned. In concrete. It shows the UARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Been cleared of all junk, trash, flow lines and und level. B) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- ind lines have been removed from lease and we hedule an inspection. CIALISTDATE09/28/2017