## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor


Ken McQueen Cabinet Secretary

Matthias Sayer

**Deputy Cabinet Secretary** 

**David Catanach** 

**Division Director** 



Field Inspection Program "Preserving the Integrity of Our Environment"

31-Oct-17

EOG Y RESOURCES, INC. 104 S. FOURTH STREET ARTESIA NM 88210

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION		
HANAGAN APL FEDERAL COM No.002H	L-31-19S-30E	30-015-39511-0

Inspection Type Inspection Date

Routine/Periodic

Inspector

Violation?

\*Significant Non-Compliance?

Corrective **Action Due By:** 

Inspection No.

Violations

Comments on Inspection:

Tony Morales

Yes

No 2/3/2018 iTM1730443040

General Housekeeping (Rule 114)

OK. All Equipment and Location in Good Shape.

PJO STAINING AROUND WELLHEAD

TUBING / SUCKER RODS FLOW LINE ON LOCATION. TANK BATTERIES OK FLARE

OK 19.15.10.8

HANAGAN APL FEDERAL COM No.003H M-31-19S-30E 30-015-39801-00-00

Inspection Date

10/31/2017

Type Inspection

Inspector

Violation?

\*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

Routine/Periodic 10/31/2017

**Tony Morales** 

Yes

No

2/3/2018

iTM1730443403

**Violations** 

General Housekeeping (Rule 114)

**Comments on Inspection:** 

OK. All Equipment and Location in Good Shape. CONVEYOR BELT UNIT OPERATING

STAINING AROUND WELLHEAD 19.15.10.8

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.