## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer

Deputy Cabinet Secretary

David Catanach
Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

06-Nov-17

## DEVON ENERGY PRODUCTION COMPANY, LP

PO Box 250

Artesia NM 88210

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		mor belle.	14 171717111	DECITOR		
HACKBER Inspection Date	RY 19 FEDERAL No.0  Type Inspection	01 Inspector	Violation?	F-19-19S-31E *Significant Non-Compliance?	30-015-30092-00- Corrective Action Due By:	00 Inspection No.
11/06/2017	Routine/Periodic	Tony Morales	Yes	No	2/9/2018	iTM1731041040
	Violations	•				
	Surface Leaks/Spills					
Comments	_	Equipment and Location in EMICAL TANKS ON LO			G AROUND WELL H 'AINING 19.15.10.9	
ARCTURU	S 18 FEDERAL COM	No.004H		M-18-19S-31E	30-015-38611-00-	00
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/06/2017	Routine/Periodic	Tony Morales	Yes	No	2/9/2018	iTM1731042130

INSPECTION DETAIL SECTION

General Housekeeping (Rule 114)

Violations

Comments on Inspection: OK. All Equipment and Location in Good Shape.

PJO. STAINING AROUND WELLHEAD

TANK BATTERIES OK CONTAINED / PORTABLE FLARE OK 19.15.10.8

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, Worden, CO

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.