Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDR'	Y NO	TICES	AND	REPO	RTS	ON V	VELLS	
na6	hi- s.	auma fau			A-:11 .			

Do not use this form for proposals to drill or to re-enter an

5. Lease Serial No. NMNM88134 6 If Indian Allottee or Tribe Name

abandoned wel	I. Use form 3160-3 (AP	D) for such p	roposals.		o. 11 maian, Anottee of	THE Name		
SUBMIT IN 1	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well ☐ Gas Well ☐ Oth	8. Well Name and No. H B 11 FEDERAL 5							
2. Name of Operator DEVON ENERGY PRODUCT	9. API Well No. 30-015-32741-00-S1							
3a. Address 6488 SEVEN RIVERS HIGHW ARTESIA, NM 88211	3b. Phone No. Ph: 405-55	(include area code) 2-7970		10. Field and Pool or Exploratory Area CEDAR CANYON-BONE SPRING				
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	1)			11. County or Parish, State			
Sec 11 T24S R29E NENW 33	0FNL 1750FWL /			EDDY COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	ΓE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA		
TYPE OF SUBMISSION	YPE OF SUBMISSION TYPE OF ACTION							
☑ Notice of Intent	☐ Acidize	□ Deep	☐ Deepen [ion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	☐ Hydi	raulic Fracturing	☐ Reclam	ation	■ Well Integrity		
☐ Subsequent Report	Casing Repair	□ New	Construction	□ Recomp	olete	Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	▼ Temporarily Abandon				
	Convert to Injection	Plug	ug Back		Disposal			
In response to Notice of Written Order DMB1707185 written by Michael Balliet, Devo- Production Company, LP respectfully requesting approval to Temporarily Abandon the production interval for the subject well per the attached procedures. Attached: Procedures Current Wellbore Proposed Wellbore Proposed Wellbore Thank you! SEE ATTACHED F					Accep	MMOCD /C		
	NOV 2 2 2 DIV CC	NDITION	IS OF APPI	ROVAL				
SUBJECT TO LIKE APPROVAL BY STATE								
	Electronic Submission # For DEVON ENERG	SY PRODUCTIO	N COM LP, sent	to the Carls	bad	<i>;</i>		
Name (Printed/Typed) ERIN WO	Title REGULATORY COMPLIANCE PROF.							
					MITHO	Luly		
Signature (Electronic S	Submission)		Date 08/28/20	017				
0010	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE			
1.0	· •	· ·	Title TPE	EZ RI	DEALL OF LAND MA	Date NACEMENT		
Attached: Procedures Current Wellbore Proposed Wellbore Thank you! NM OIL CONSERVATION ARTESIA DISTRICT ARTESIA DISTRICT SEE ATTACHED FOR NOV 2 2 2017 CONDITIONS OF APPROVAL SUBJECT TO LIKE APPROVAL BY STATE 4. I hereby certify that the foregoing is true and correct. Electronic Submission #386346 verified by the BLM Well Information System For DEVON ENERGY PRODUCTION COM LP., sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 09/27/2017 (17PP0988SE) Name (Printed/Typed) ERIN WORKMAN Title REGULATORY COMPLIANCE PROF. THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations a	s to any matter wi	rson knowingly and thin its jurisdiction.	willfully to m	ake to any department or	agency of the United		

DVN: H B 11 Federal #5

API #30-015-29625

Sec 11-T24S-R29E Eddy County, NM 8/25/2017

Purpose: Temporarily Abandon 2nd Bone Spring Production Interval

T.D. - 8,497' PBTD - 8,408'; CIBP to be SET @ -6,850' w/ 35' cmt on top (6,815')

Wellbore fluid: Formation oil, natural gas and formation water.

Casing and Tubing Data:

Size	Wt. lb/ft	Grade	Interval	(.80 S. F.) Collapse	(.80 S. F.) Burst	Drift	Capacity (bbls/ft)
13-3/8"	48	H-40	0 - 560'	600	1,375	12.559"	
8-5/8"	32	J-55	0 - 3,110'	2,000	3,100	7.796"	
5-1/2"	17	K-55	0 - 8,497'	3,930	4,250	4.767"	0.0232
2-7/8"	6.5	L-80	0 - 8,193'	8,925	8,450	2.347"	0.00579

2-7/8" by 5-1/2" – 0.0152 bbls/ft.

5-1/2" - 0.1305 ft3/ft

Top of Cement: To be validated via Cement Bond Log during procedure

Current Perfs:

2nd Bone Spring Sandstone

7,956'-7,963' (7')

8,108'-8,121' (13')

8,128'-8,132' (4')


HB 11 Federal #5 Procedure:


- 1. Remove PR and Stuffing Box. Install Rod rams. Unseat pump and T.O.H. with rods and pump.
- 2. ND wellhead. NU 5,000 psi BOPE, w/1 set of blind rams on bottom plus 1 set of 2-7/8" tbg rams on top. Test BOPE to Devon specifications.

3. Unset TAC @ ~7,902'. T.O.H. within 7850'-7940'

- 4. TIH and set CIBP at 6,850. Cap CIBP with 35'cement (minimum 25 sacks) for a PBTD of 6,815. Wait on cement.
- 5. TIH and tag top of cement to verify sufficient cap. TOOH tubing string.

- 6. Run casing integrity log and CBL. Submit results to BLM and verify top of cement above proposed perforated interval.
- 7. Fill wellbore with corrosion inhibited water. Utilize fresh water with vendor supplied corrosion inhibiting chemical.
- 8. Contact BLM prior to executing this step. MIT the 5-1/2" csg to 500 psi at surface for 30 min with a 1000 psi chart recorder and submit results to BLM with corrosion inhibited fluid.
- 9. R.D.M.O. DDCU and release all rentals. Shut in all tubing and casing valves.





Conditions of Approval Devon Energy Production Company

H B - 05, API 3001532741 T24S-R29E, Sec 11, 330FNL & 1750FWL November 8, 2017

Begin wellbore operations within 90 days of these conditions of approval for the processed Electronic Submission #386346 notice of intent or request an extension.

Well has no record of beneficial use since month of 02/2017.

Operator is to have this NOI approved preparation procedure for temporary abandonment with applicable conditions of approval on location for this workover operation.

A temporarily abandoned well defined as a completion not capable of production in paying quantities but which may have value as a service well.

Temporary Abandonment (TA) BLM Status Approval Requires:

- 1. A Notice of Intent (NOI) Sundry (Form 3160-5) requesting approval to prepare the wellbore for a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A subsequent sundry report that describes compliance:
 - a. All downhole production artificial lift equipment (tubing, rods, etc.) removed from casing. A wellbore with a packer set just above producing or injection perforations with annulus integrity above the packer, and loaded with corrosion inhibiting fluid considered for TA status by passing a Mechanical Integrity Test.
 - b. A cast iron bridge plug or packer installed within 100 feet above perforations or open hole of open formations.
 - c. Where the formation may be reopened 35 feet cement bailed on the CIBP is sufficient.
 - d. Open formations below potential production plugged back per permanent plugging procedures. Set a CIBP above the top perforations of a formation permanently abandoned and cap with a minimum of 25 sacks cement placed with tubing. Also, cover the formation top with a minimum of 25 sacks cement placed with tubing. A cement plug requires the top of the set cement verified by a tubing tag.
 - e. At least 24 hours prior to conducting the Mechanical Integrity Test, contact the appropriate BLM office. Eddy County call Carlsbad 575-361-2822.
 - f. Documentation of a 500psig minimum BLM witnessed Mechanical Integrity Test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff viewed as a failed MIT. Verify all annular casing vents plumbed to surface and those valves open to the surface during this pressure test. Pressure leakoff will be evaluated site specifically and affect approvals.

- 3. Submit a Subsequent Sundry Notice (Form 3160-5) requesting TA approval with a description of the preparation for temporary abandonment approval, a clear copy or the original Mechanical Integrity Test chart, an electronic copy of the proposed CBL, and justification for not plugging. Justification is listing the proposed beneficial use and reasonable expected dated events to initiate a conversion to beneficial use. Often overlooked is a backlog of wells that have no potential beneficial use (should have been plugged and abandoned) that create a status surplus.
- 4. This BLM TA NOI Approval is for WELLBORE PREPARATION ONLY. BLM IS NOT APPROVING TA Status FOR THIS WELL. If warranted, TA approval status for a specified time limit noted with BLM acceptance of the subsequent report of preparations and justification.
- 5. Should Mechanical Integrity Test not prove wellbore integrity or not be conducted submit a procedure to repair or plug and abandon the well for BLM approval within 30 days of the MIT.