State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary **David Catanach** Division Director



Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

03-Jan-18

BOPCO, L.P. 6401 Holiday Hill Rd Bldg 5, Ste 200 Midland TX 79707-9707

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTIO	N DETAIL	SECTION			
JAMES RANCH UNIT No.030 Inspection Date Type Inspection)30 Inspector	Violation?	J-6-23S-31E *Significant Non-Compliance?	30-015-27704-00- Corrective Action Due By:	00 Inspection No.	
01/03/2018	Routine/Periodi Violations General Housekeep	,	Yes	No	4/8/2018	iTM1800341413	
Comments	-	OK. All Equipment and Location in CHEMICAL TANK 19.15.10.8	Good Shape	PJ STAINING	AROUND WELLHE	AD /	
JAMES RANCH UNIT No.065 Inspection Date Type Inspection)65 Inspector	Violation?	B-6-23S-31E *Significant Non-Compliance?	30-015-27995-00- Corrective Action Due By:	00 Inspection No.	
01/03/2018	Routine/Periodi Violations General Housekeep		Yes	No	4/8/2018	iTM1800339746	
		OK. All Equipment and Location in ROUND WELL HEAD 19.15.10	uipment and Location in Good Shape. WELL HEAD 19.15.10.8		. PJ POWER OFF / TAGGED. STAINING		

JAMES RA Inspection Date	NCH UNIT N Type Inspectio	-	Violation?	K-6-23S-31E *Significant Non-Compliance?	30-015-33114-00- Corrective Action Due By:	00 Inspection No.
01/03/2018	Routine/Peri	odic Tony Mor	ales Yes	No	4/8/2018	iTM1800341640
	Violations					
Comments on Inspection:		OK. All Equipment and Location in Good Shape. 19.15.10.8		PJ STAINING AROUND WELLHEAD.		

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

s, co. ona Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.