State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary David Catanach Division Director



Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

26-Jan-18

BOPCO, L.P.

6401 Holiday Hill Rd Bldg 5, Ste 200 Midland TX 79707-9707

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTI	ON DETAIL	SECTION		
POKER LAKE UNIT Inspection Date Type Inspection		No.083 Inspector	Violation?	D-30-24S-31E *Significant Non-Compliance?	30-015-27753-00-0 Corrective Action Due By:)0 Inspection No.
01/26/2018	Routine/Period Violations General Housekee	,	Yes	No	5/1/2018	iTM1802641399
Comments	-	OK. All Equipment and Location 19.15.10.8	in Good Shape.	PJO. STAINING A	AROUND WELL HEA	\D
POKER LA Inspection Date	KE UNIT Type Inspection	No.086 Inspector	Violation?	L-19-24S-31E *Significant Non-Compliance?	30-015-27912-00-0 Corrective Action Due By:)0 Inspection No.
01/26/2018	Routine/Period Violations General Housekee	, , , , , , , , , , , , , , , , , , ,	Yes	No	5/1/2018	iTM1802641775
Comments on Inspection:		OK. All Equipment and Location 19.15.10.8	in Good Shape	PJO. STAINING A	AROUND WELL HEA	\D

POKER LA Inspection Date	KE UNIT No. Type Inspection		Violation?	C-20-24S-31E *Significant Non-Compliance?	30-015-40296-00- Corrective Action Due By:	00 Inspection No.			
01/26/2018	Routine/Perio	dic Tony Morales	Yes	No	5/1/2018	iTM1802644186			
	Violations								
Absent Well Identification Signs (Rule 103)									
Comments on Inspection: OK		OK. All Equipment and Location in	All Equipment and Location in Good Shape.		LOCATION SIGN NOT VISIBLE 19.15.16.8				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia QCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.