## State of New Mexico Energy, Minerals and Natural Resources Department

## Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary David Catanach Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

06-Feb-18

BOPCO, L.P. 6401 Holiday Hill Rd Bldg 5, Ste 200 Midland TX 79707-9707

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTI	ON DETAIL	SECTION		
POKER LAKE UNIT No.190 Inspection Date Type Inspection		90 Inspector	Violation?	J-7-24S-30E *Significant Non-Compliance?	30-015-32142-00- Corrective Action Due By:	00 Inspection No.
02/06/2018	Routine/Period Violations General Housekeep	-	s Yes	No	5/12/2018	iTM1803741033
Comments		OK. All Equipment and Location 19.15.10.8	i in GoodShape.	PJO. STAININ	G AROUND WELL I	HEAD
POKER LAKE UNIT No.204 Inspection Date Type Inspection		04 Inspector	Violation?	N-7-24S-30E *Significant Non-Compliance?	30-015-32928-00- Corrective Action Due By:	00 Inspection No.
02/06/2018	Routine/Period Violations General Housekeep	,	s Yes	No	5/12/2018	iTM1803743700
Comments	-	OK. All Equipment and Location 19.15.10.8	in Good Shape	. PJ. STAINING	G AROUND WELL H	EAD

Inspection	KE UNIT No		Improved	Violation?	N-6-24S-30E *Significant	30-015-33161-00-0 Corrective	)) Inspection No.
Date	Type Inspectio		Inspector		Non-Compliance?	Action Due By:	•
02/06/2018	Routine/Periodic		Tony Morales	Yes	No	5/12/2018	iTM1803737791
	Violations						
	General Housek	eeping (Rule 114)					
<b>Comments</b>	on Inspection:	OK. All Equip HEAD 19.15.	ment and Location in 10.8	1 Good Shape.	PJO. STAININ	NG AROUND WELL	
POKER LA Inspection Date	KE UNIT No Type Inspectio		Inspector	Violation?	M-8-24S-30E *Significant Non-Compliance?	30-015-33642-00-( Corrective Action Due By:	)0 Inspection No.
02/06/2018	Routine/Periodic		Tony Morales	Yes	No	5/12/2018	iTM1803744516
02,00,2010	Violations		rony monutos	105	110	5,12,2010	
		ntification Signs (	Rule 103)				
Comments on Inspection: OK. All Equipm 19.15.16.8			oment and Location ir	n Good Shape	. PJO LOCATI	ON SIGN NOT VISIB	ILE
POKER LA	KE CVX JV	PC No.008H			D-7-24S-30E	30-015-37029-00-0	00
Inspection Date	Type Inspectio	n	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/06/2018	Routine/Periodic Violations		Tony Morales	Yes	No	5/12/2018	iTM1803737386
			quipment and Location in Good Shape. PJO. STAINING AROUND WELL 9.15.10.8				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, Artesia CD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.