## NM OIL CONSERVATION

ARTESIA DISTRICT

| Submit One Copy To Appropriate District  | State of New Me                        | exico          | JAN <b>3 0</b> 2018 Form C-103   |
|--|--|----------------|--|
| Office District I  | Energy, Minerals and Natu              | ıral Resources | Revised November 3, 2011   |
| 1625 N. French Dr., Hobbs, NM 88240<br>District II   |  |                | <b>NECEIMHI</b> NO.<br>30-015-32000  |
| 811 S. First St., Artesia, NM 88210<br>District III  | OIL CONSERVATION<br>1220 South St. Fra |                | 5. Indicate Type of Lease  |
| 1000 Rio Brazos Rd., Aztec, NM 87410   |  |                | STATE X FEE  |
| District IV<br>1220 S. St. Francis Dr., Santa Fe, NM<br>87505  | Santa Fe, NM 8                         | 7303           | 6. State Oil & Gas Lease No.   |
|  | S AND REPORTS ON WELLS                 | 3              | 7. Lease Name or Unit Agreement Name   |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  |  |                | LUCY ALC STATE   |
| PROPOSALS.)  1. Type of Well: X Oil Well  Gas Well  Other  |  |                | 8. Well Number 04  |
| 2. Name of Operator<br>EOG Y RESOURCES, IN   | , , , , , , , , , , , , , , , , , , ,  |                | 9. OGRID Number<br>25575   |
| 3. Address of Operator   |  |                | 10. Pool name or Wildcat   |
| PO BOX 2267 MIDLAN   | D, TEXAS 79702                         |                | LOST TANK; DELAWARE  |
| 4. Well Location   |  |                | A CONTRACTOR OF THE PROPERTY O |
| Unit Letter G: 1980 feet from the NORTH line and 2080 feet from the EAST line  |  |                |  |
| Section 34 Township 21S Range 31E NMPM County EDDY   |  |                |  |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3488' GL  |  |                |  |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data   |  |                |  |
|  |  |                |  |
| NOTICE OF INTE   |  | I .            | SEQUENT REPORT OF:  K  |
| <u></u>  | PLUG AND ABANDON  CHANGE PLANS         | REMEDIAL WOR   |  |
|  | MULTIPLE COMPL                         | CASING/CEMEN   |  |
|  |  |                |  |
| OTHER:   |  |                |  |
| All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. |  |                |  |
| Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the        |  |                |  |
| OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR  |  |                |  |
| UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR  |  |                |  |
| PERMANENTLY STAMPED ON THE MARKER'S SURFACE.  The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and   |  |                |  |
| other production equipment.  |  |                |  |
| Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.  |  |                |  |
| If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with   |  |                |  |
| OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.   |  |                |  |
| All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have   |  |                |  |
| to be removed.)  |  |                |  |
| All other environmental concerns have been addressed as per OCD rules.   |  |                |  |
| Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-   |  |                |  |
| retrieved flow lines and pipelines.  If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well.  |  |                |  |
| location, except for utility's distribution infrastructure.  |  |                |  |
| When all work has been completed, return this form to the appropriate District office to schedule an inspection.   |  |                |  |
| of Ma  | d d m/                                 |                |  |
| SIGNATURE LAY MAN  | TITLE: I                               | REGULATORY SP  | ECIALIST DATE 01/30/2018   |
| TYPE OR PRINT NAME: KAY MA   |  |                |  |
| For State Use Only   |  |                | <del></del>  |
| APPROVED BY:   | 210 TITLE                              | Staff m.       | DATE /-31-18   |
| Conditions of Approval (if any)  |  | ····/          |  |