Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103 Revised July 18, 2013	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION		30-015-34671	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	, , , , , , , , , , , , , , , , , , , ,			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Wright JA	
PROPOSALS.) 1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other			8. Well Number 6	
2. Name of Operator			9. OGRID Number	
EOG Y Resources, Inc.			025575	
3. Address of Operator104 South Fourth Street, Artesia, NM 88210			10. Pool name or Wildcat Atoka; Glorieta-Yeso	
4. Well Location				
Unit Letter <u>F</u> :	2310 feet from the Nort	h line and	1650 feet fro	om the <u>West</u> line
Section 34		inge 26E		ddy County
and an	11. Elevation <i>(Show whether DF</i>)	
3357' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	CHANGE PLANS	SUE REMEDIAL WOR COMMENCE DR CASING/CEMEN	ILLING OPNS.	EPORT OF: ALTERING CASING P AND A
CLOSED-LOOP SYSTEM) M	OTHER: Acidize	2	\boxtimes
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 				
 2/1/18 – MIRU and opended up well. Had 100 psi on casing, no pressure on tubing. Tried to load tubing with 40 bbls 2% KCL. Did not load. POOH with pump. Pumped 40 bbls 2% KCL to kill casing. NU BOP. 2/2/18 – Had 150 psi on casing, no pressure on tubing. Pumped 40 bbls 2% KCL to kill well. POOH with tubing. Tagged up at 3471' and tried bailing down. No progress. Rotated down to 3503'. Spotted 2000g 15% NEFE HCL acid across perforations. Displaced with 				
10 bbls 2% KCL. 2/3/18 – Pumped 4 bbls 2% KCL. Set 2-7/8" 6.5# J-55 tubing at 3452'. Flushed tubing with 20 bbls 2% KCL with corrosion inhibitor, biocide and 02 scavenger before seating pump. Loaded tubing with 11 bbls treated 2% KCL. Pressure tested to 500 psi, held good. Longstroke pump twice to 500 psi, good. Turned well over to production.				
			NŅ	ANIBEOGESEATION
				FFFEB 2 0 2018
Spud Date:	Rig Release D	ate:		RECEEVED
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE (Jine)		ulatory Specialist		February 15, 2018
Type or print name <u>Tina Hu</u> For State Use Only	ierta E-mail address: tin	a_huerta@eogresou	rces.com PH	IONE: <u>575-748-4168</u>
APPROVED BY: Conditions of Approval (if any):	TITLE STAT	A Mg	D	DATE 2-21-18