

State of New Mexico  
Energy, Minerals and Natural Resources Department

**Susana Martinez**  
Governor

**Ken McQueen**  
Cabinet Secretary

**Matthias Sayer**  
Deputy Cabinet Secretary

**Heather Riley**  
Division Director



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

26-Feb-18

**OXY USA INC**  
PO Box 4294  
Houston TX 77210-7210

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.


***INSPECTION DETAIL SECTION***

<b>CEDAR CANYON 22 FEDERAL COM</b>		<b>No.004H</b>	<b>I-22-24S-29E</b>	<b>30-015-43708-00-00</b>		
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805742400
<b>Violations</b>						
Absent Well Identification Signs (Rule 103)						
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8 TEX MEX HOBBS NM SPOKE TO RAY WORKING ON HEADER FOR METHANOL TO KEEP PUMPS FROM FREEZING						
<b>CEDAR CANYON 22 15 FEE</b>		<b>No.032H</b>	<b>C-22-24S-29E</b>	<b>30-015-43808-00-00</b>		
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805741903
<b>Violations</b>						
Absent Well Identification Signs (Rule 103)						
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8 FRAC TANKS ON LOCATION WHITE POLYPIPE STORED ON LOCATION						

<b>CEDAR CANYON 22 15 FEE</b>				<b>No.031H</b>	<b>C-22-24S-29E</b>	<b>30-015-43809-00-00</b>	
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>	
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805742013	
<b>Violations</b>							
Absent Well Identification Signs (Rule 103)							
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8							
<b>CEDAR CANYON 16 STATE No.034H</b>				<b>A-16-24S-29E</b>	<b>30-015-43843-00-00</b>		
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>	
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805736650	
<b>Violations</b>							
Absent Well Identification Signs (Rule 103)							
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8							
<b>CEDAR CANYON 16 STATE No.033H</b>				<b>A-16-24S-29E</b>	<b>30-015-43844-00-00</b>		
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>	
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805736570	
<b>Violations</b>							
Absent Well Identification Signs (Rule 103)							
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8							
<b>CYPRESS 34 FEDERAL No.012H</b>				<b>A-3-24S-29E</b>	<b>30-015-43849-00-00</b>		
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>	
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805738928	
<b>Violations</b>							
Absent Well Identification Signs (Rule 103)							
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8 SPOKE TO BEN ACKMAN TECH SIGNAGE LOCATION MAINTENANCE							
<b>CEDAR CANYON 23 24 FEDERAL</b>				<b>No.031H</b>	<b>A-22-24S-29E</b>	<b>30-015-44179-00-00</b>	
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>	
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805741005	
<b>Violations</b>							
Absent Well Identification Signs (Rule 103)							
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8 FRAC TANKS ON LOCATION							
<b>CEDAR CANYON 23 24 FEDERAL No.032H</b>				<b>A-22-24S-29E</b>	<b>30-015-44180-00-00</b>		
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>	
02/26/2018	Routine/Periodic	Tony Morales	Yes	No	6/1/2018	iTM1805741104	
<b>Violations</b>							
Absent Well Identification Signs (Rule 103)							
<b>Comments on Inspection:</b> OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE 19.15.16.8 FRAC TANKS ON LOCATION STAINING THROUGHOUT LOCATION							

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



Artesia OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.