State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen

Cabinet Secretary

Matthias Sayer

Deputy Cabinet Secretary

Heather Riley

Division Director



Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

07-Mar-18

DEVON ENERGY PRODUCTION COMPANY, LP

PO Box 250

Artesia NM 88210

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

DOC HOLLIDAY 32 STATE COM Inspection			No.001		D-32-24S-27E *Significant	30-015-41145-00-00 Corrective	0
Date	Type Inspection	1	Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
03/07/2018	Routine/Periodic		Tony Morales	Yes	No	6/10/2018	iTM1806647118
Violations							
	General Houseke	ekeeping (Rule 114)					
Comments	on Inspection:		nent and Location in IK BATTERIES OF			AROUND WELLHEAD	
PREACHER 19 FEDERAL No.0031					O-19-24S-27E	30-015-41887-00-0	0
Inspection Date	Type Inspection		Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/07/2018	Routine/Perio	dic	Tony Morales	Yes	No	6/10/2018	iTM1806648473
	Violations						
	Surface Leaks/Sp	oills					
General Housekeeping (Rule 114)							
Comments on Inspection:		OK. All Equipment and Location in Good Shape. TANK BATTERIES OK FLARE / SEPARATOR AREA STAINING 19.15.10.8 APPROX. STAINED AREA -SEPARATOR 50' X 200' FLARE AREA 50' X 125'					

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.