Form 3160-5 (June 2015) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					OMB N	APPROVED O. 1004-0137 anuary 31, 2018
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agre	ement, Name and/or No.	
Type of Well Gas Well Gas Well Other Contact: MIKE PIPPIN LIME ROCK RESOURCES II-A, L.P. E-Mail: MIKE@PIPPINLLC.COM					 8. Well Name and No. HAWK 9 G FEDERAL 19 9. API Well No. 30-015-43216 	
3a. Address 3b. Phone No. C/O MIKE PIPPIN 3104 N. SULLIVAN Ph: 505-32 FARMINGTON, NM 87401 87401			(include area code) 7-4573 10. Field and Pool or Exploratory Area RED LAKE, GL-YESO 51120			
4. Location of Well <i>(Footage, Sec., 1</i> Sec 9 T18S R27E SWNE 227		11. County or Parish, State EDDY COUNTY, NM				
12. CHECK THE AL	PPROPRIATE BOX(ES) TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTI	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
 Notice of Intent Subsequent Report Final Abandonment Notice 	Alter Casing Casing Repair Change Plans		epen draulic Fracturing w Construction g and Abandon g Back	 Recomplete Temporarily Abandon Water Disposal 		 Water Shut-Off Well Integrity Other Surface Rehabilitati on
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. THIS NEW WELL IS READY FOR INTERIM REMEDIATION INSPECTION. This new well was completed on 10/19/16. The location has been down sized and reseeded and is now ready for inspection. MAR 1 9 2013 INFORMATION INSPECTION INFORMATION INSPECTION INFORMATION INSPECTION BURIAU OF LAND MANAGEMENT OF DEPIVED BURIAU OF LAND MANAGEMENT OF DEPIVED						
$\frac{10170117701}{14. 1 \text{ hereby certify that the foregoing is}}$	s true and correct. Electronic Submission a	#371224 verifie RESOURCES	d by the BLM Wel I-A, L.P., sent to	the Carlsba	CARLEBAD [[E][n System d	
Name (Printed/Typed) MIKE PIPPIN			Title PETROLEUM ENGINEER			
Signature (Electronic Submission) Date 03/27/2017						
	THIS SPACE F			OFFICE U	SE	
Approved By						
	,	,	,		······································	

N

(Instructions on page 2) ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **