NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico Energy Minerals and Natural Resources MAR 29 2018

Form C-141 Revised April 3, 2017

RECEIVED
Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action													
MAB 181	0893	9025			OPERA	FOR		🛛 Initia	al Report	N/	Final Report		
<u> </u>							Contact Eli Trevino						
Facility Na			4/3 Hou	ston, 1X //002	Telephone No. (575) 499-3993 Facility Type Salt Water Disposal								
·] N.G1.G									
Surface Owner Mineral Owner Private API No. 30-015-22321													
T T 1 T 4	Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County												
B Unit Letter	Section 7	1 ownship 19S	Range 26E	660	North/:	South Line	1980	East/\ East	vest Line	Eddy			
	<u> </u>		<u> </u>	<u> </u>	<u></u>								
Latitude 32.6808357 Longitude -104.41922 NAD83													
NATURE OF RELEASE													
Type of Release Water							Volume of Release 125 bbls Volume Recovered 12						
Source of Release Third Party							Date and Hour of Occurrence Date and 3/25/2018 3/25/2018				Hour of Discovery		
Was Immediate Notice Given?							If YES, To Whom?						
			Yes 🗆	No Not R	Crystal Weaver (NMOCD) and Mike Bratcher (NMOCD) by email								
By Whom? Toby Rhodes							Date and Hour 3/26/2018 5:00 PM						
Was a Watercourse Reached? ☐ Yes ☒ No							If YES, Volume Impacting the Watercourse.						
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	*		<u> </u>		······································				······································	
If a Watercourse was Impacted, Describe Fully.* No watercourse impacted.													
Describe Cause of Problem and Remedial Action Taken.* On March 25, 2018, a Percussion employee discovered water standing inside the lined containment area at the battery for the subject well. As soon as a													
vacuum truck became available (March 26, 2018), the standing water was vacuumed up from inside the area. We recovered all the fluid inside the													
containment area.													
		and Cleanup and a		ken.* eadings were revi	ewed W	e were unabl	e to find any evid	ence of	a leak or a	tank overflo	w. We l	believe that	
it is likely the				er at our site. We									
MST.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations a	ll operators	are required t	o report a	nd/or file certain i	release no	otifications a	nd perform correc	tive act	ions for rele	eases which	may en	ıdanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state	, or local la	ws and/or reg	ulations.				OH COM	CEDY	ATION	DIMOIC			
						OIL CON	SEK V	AHON	DIAISIC	<u> </u>			
Signature:	m_ 1	Approved by Environmental Specialist / Security											
Printed Name	e: Michael l	1	Approved by	Environmental S	pecialis	EMP X	OKAMENE.	<u> </u>	***				
				A 1 75	_{te:} 3/30/18		77_	D	IA				
Title: Petrole	um Engine	3				Approval Da	ie: 4/20110		Expiration	Date: N I	11		
E-mail Address: Michael@percussionpetroleum.com						Conditions of Approval; Attached				دیم دا			
Date: 3/29/2018 Phone: (713) 429-4249						FINAL				0	XKP-4U81		