

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

MAR 29 2018

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
concordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1808940343

37115

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company: Rockcliff Operating New Mexico LLC	Contact: John Turner
Address: 1301 McKinney St, Suite 1300, Houston, TX 77010	Telephone No.: 903-643-3791
Facility Name : El Toro Tank Battery (Invicta 14 221H)	Facility Type: Oil and Gas Production Facility

Surface Owner: Uffie Land Company	Mineral Owner: Multiple	API No. 30-015-44091
-----------------------------------	-------------------------	----------------------

## LOCATION OF RELEASE

Unit Letter M	Section 14	Township 23S	Range 28E	Feet from the 340	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.298937 Longitude -104.064916 NAD 83

## NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 9 MCF	Volume Recovered: 0
Source of Release: Compressor	Date and Hour of Occurrence: 03/17/18, 0447hrs	Date and Hour of Discovery 03/17/17, 0515hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gilbert Cordero	
By Whom? John Turner	Date and Hour: 03/17/18, 0932hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Cat 3508ULB Compressor on location caught fire at approximately 0447hrs from the starter exhaust vent. Night operator shut-in wells at approximately 0520hrs. Fire department arrived on location and extinguished fire.		
Describe Area Affected and Cleanup Action Taken.* There was no impact to ground or remedial action taken. The fire burned the natural gas.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Mike Martin</u>	OIL CONSERVATION DIVISION	
Printed Name: Mike Martin	Approved by Environmental Specialist: <u>Mike Martin</u>	
Title: Field Operations Manager	Approval Date: <u>3/30/18</u>	Expiration Date: <u>N/A</u>
E-mail Address: mike.martin@rockcliffenergy.com	Conditions of Approval: <u>FINAL</u>	Attached <input checked="" type="checkbox"/> <u>220-4683</u>
Date: 12/5/17	Phone: 903-643-3791	

\* Attach Additional Sheets If Necessary