State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary Matthias Saver

Deputy Cabinet Secretary

Heather RileyDivision Director



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

27-Mar-18

CIMAREX ENERGY CO. OF COLORADO

202 S. Cheyenne Ave, Ste 1000 Tulsa OK 74103-4103

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO	N DETAIL	SECTION		
FEDERAL 13 COM Inspection Date Type Inspection			0.002 Inspector	Violation?	K-13-25S-26E *Significant Non-Compliance?	30-015-33344-00- Corrective Action Due By:	O Inspection No.
03/27/2018	Routine/Perio	•			No	6/30/2018	iTM1808636357
Comments	on Inspection:	OK. All Equi 19.15.10.8	ipment and Location in	Good Shape.	TANK BATTERIE	S STAINING / LOCA	TION
WIGEON 23 FEDERAL COM Inspection Date Type Inspection			No.001 Inspector	Violation?	J-23-25S-26E *Significant Non-Compliance?	30-015-33563-00- Corrective Action Due By:	00 Inspection No.
03/27/2018	Routine/Perio		Tony Morales	Yes	No	6/30/2018	iTM1808640159
Comments	on Inspection:		ipment and Location in TUBING / DEBRIS O			ES AREA STAINING	OLD

WIGEON 23 FEDERAL COM		No.002		H-23-25S-26E 30-015-33684-00-00			
Inspection Date	Type Inspection	•	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/27/2018	Routine/Perio	odic eeping (Rule 114)	Tony Morales	Yes	No	6/30/2018	iTM1808637971
Comments on Inspection: OK. All Equi		ment and Location ir		TANK BATTERIE	S / LOCATION STAI	NING	
PINTAIL 23 FEDERAL No.003					F-23-25S-26E	30-015-36335-00-00	
Inspection Date	Type Inspectio	n	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/27/2018	Routine/Perio	odic eeping (Rule 114)	Tony Morales	Yes	No	6/30/2018	iTM1808639202
Comments	on Inspection:		ment and Location in S MONITOR OK	n Good Shape.	PJ TANK BATTEI	RIES STAINING	
WHITE CIT	TY 14 FEDERAL No.004 Type Inspection		Inspector Violation?		O-14-25S-26E *Significant Non-Compliance?	30-015-36336-00-00 Corrective Action Due By: Inspection No.	
03/27/2018	Routine/Perio	odic eeping (Rule 114)	Tony Morales	Yes	No	6/30/2018	iTM1808636971
Comments	on Inspection:	OK. All Equip	ment and Location in 2S MONITOR OK	1 Good Shape.	. PJ TANK BATTE	RIES STAINING	
FEDERAL	FEDERAL 13 COM N		0.006		C-13-25S-26E	30-015-36571-00-00	
Inspection Date	Type Inspection	n	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/27/2018	Routine/Perio	odic eeping (Rule 114)	Tony Morales	Yes	No	6/30/2018	iTM1808635627
Comments	on Inspection:	OK. All Equip	ment and Location in	n Good Shape	. TANK BATTERIE	S STAINING 19.15.1	0.8
Inspection	3 26 FEDERA		No.010H	T. 1 4' .9	C-23-25S-26E *Significant	30-015-43773-00-Corrective	
Date	Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
03/27/2018	Routine/Periodic Violations Absent Well Identification Signs (R		Tony Morales	Yes	No	6/30/2018	iTM1808638523

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

OK. All Equipment and Location in Good Shape. LOCATION SIGN WRONG SECTION "13"

Sincerely,

Comments on Inspection:

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.