

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

FORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018

5. Lease Serial No.  
NMNM7717

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
HONDO 4 K FEDERAL 51

9. API Well No.  
30-015-44017-00-X1

10. Field and Pool or Exploratory Area  
RED LAKE

11. County or Parish, State  
EDDY COUNTY, NM

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
LIME ROCK RESOURCES II A LP  
Contact: MIKE PIPPIN  
E-Mail: MIKE@PIPPINLLC.COM

3a. Address  
1111 BAGBY STREET SUITE 4600  
HOUSTON, TX 77002

3b. Phone No. (include area code)  
Ph: 505-327-4573

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Sec 4 T18S R27E NESW 1750FSL 1655FWL

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Well Spud
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

THIS IS THE SPUD & CASING REPORT FOR A NEW OIL WELL:

Spudded well on 2/12/18. Drilled 12-1/4" hole to 360'. Set 8-5/8" 24# J-55 csg @ 349'. Cmted 11500 lb cement slurry (469 cf) cl "C" cmt w/2% CaCl<sub>2</sub> & 0.125#/sx cello flakes. Circ. 125 sx cmt to surface. On 2/13/18, pressure tested 8-5/8" csg to 1500 psi for 30 min-OK. Drilled 7-7/8" hole to TD4820' on 2/17/18. On 2/18/18, set 5-1/2" 17# J-55 production csg @ 4809'. Cmted lead w/300 sx (588 cf) 35/65 poz cl "C" w/6% gel/PF20, 5% salt/PF44, 0.2% fluid loss/PF606, 0.125#/sx cello flake/PF29, 0.4#/sx antifoamer/PF45, 0.1% retarder/PF13 & 3#/sx kolseal/PF42. Tailed w/600 sx (798 cf) cl "C" cmt w/0.2% fluid loss/PF606, 0.2% dispersant/PF65, & 0.125#/sx cellophane/PF29. Did not circ cmt. Contacted BLM. Ran temp survey, which showed cmt @ 10'. Released drilling rig on 2/19/18. Plan to pressure test 5-1/2" csg during completion operations.

**BLM OIL CONSERVATION  
ARTESIA DISTRICT**

APR 12 2018

**RECEIVED**

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #404978 verified by the BLM Well Information System  
For LIME ROCK RESOURCES II A LP, sent to the Carlsbad  
Committed to AFMSS for processing by PRISCILLA PEREZ on 02/22/2018 (18PP1184SE)**

Name (Printed/Typed) MIKE PIPPIN

Title PETROLEUM ENGINEER

Signature (Electronic Submission)

Date 02/20/2018

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By **ACCEPTED**

(B Pending BLM approvals will  
subsequently be reviewed  
and scanned

04/02/2018

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office C.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowing States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

Additional data for EC transaction #404978 that would not fit on the form

32. Additional remarks, continued

**Revisions to Operator-Submitted EC Data for Sundry Notice #404978**

	<b>Operator Submitted</b>	<b>BLM Revised (AFMSS)</b>
Sundry Type:	SPUD SR	SPUD SR
Lease:	NMNM7717	NMNM7717
Agreement:		
Operator:	LIME ROCK RESOURCES II-A, L.P. C/O MIKE PIPPIN 3104 N. SULLIVAN FARMINGTON, NM 87401 Ph: 505-327-4573	LIME ROCK RESOURCES II A LP 1111 BAGBY STREET SUITE 4600 HOUSTON, TX 77002 Ph: 713.292.9510
Admin Contact:	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: MIKE@PIPPINLLC.COM  Ph: 505-327-4573	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: MIKE@PIPPINLLC.COM  Ph: 505-327-4573
Tech Contact:	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: MIKE@PIPPINLLC.COM  Ph: 505-327-4573	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: MIKE@PIPPINLLC.COM  Ph: 505-327-4573
Location:		
State:	NM	NM
County:	EDDY	EDDY
Field/Pool:	RED LAKE, GL-YESO NE 96836	RED LAKE
Well/Facility:	HONDO 4 K FEDERAL 51 Sec 4 T18S R27E NESW 1750FSL 1655FWL	HONDO 4 K FEDERAL 51 Sec 4 T18S R27E NESW 1750FSL 1655FWL