| Submit 3 Copies To Appropriate District Office | State of New Mexico |) | Form C-103 | |
|---|---|----------------------------|--|--|
| District I | Energy, Minerals and Natural I | Resources | May 27, 2004 | |
| 1625 N. French Dr., Hobbs, NM 88240 District II | | WELL API 30-005-6380 | ì | |
| 1301 W. Grand Ave., Artesia, NM 88210 | OIL CONSERVATION DI | V V | Type of Lease | |
| District III | 1220 South St. Francis | Dr. STA | | |
| 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> | Santa Fe, NM 87505 | 6. State Oil | & Gas Lease No. | |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH | | ACK TO A | nme or Unit Agreement Name | |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other | | | 8. Well Number | |
| 1. Type of Well: Oil Well | - | 001 | | |
| 2. Name of Operator | RECE | 7. 00102 | Number | |
| Gruy Petroleum Management Co. | APR 1 | 7 7006 162683 | 33773.1 | |
| 3. Address of Operator | | 10. 1001114 | me or Wildcat lley; Penn (Prorated Gas) | |
| PO Box 140907; Irving, TX 7501 | 4-0907 OCU-N | Dullalo va | niey, Feim (Florated Gas) | |
| 4. Well Location | | | | |
| Unit Letter M: 1085 feet from the South line and 1165 feet from the West line | | | | |
| Section 8 Township 15S Range 28E NMPM County Chaves | | | | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3533' GR | | | | |
| Pit or Below-grade Tank Application or Closure | | | | |
| Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water | | | | |
| Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material | | | | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | | | |
| 12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data | | | | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | | | |
| PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ | | | | |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A | | | | |
| PULL OR ALTER CASING | MULTIPLE COMPL CA | SING/CEMENT JOB | | |
| OTHER: | | HER: | П | |
| | pleted operations. (Clearly state all perti | | nt dates, including estimated date | |
| of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion | | | | |
| or recompletion. | | | | |
| 02.16.06 | 0.2/4211- (01002) | | | |
| | 8-3/4" hole (9100'). | Commented first stage with | lood of 250 ov Intenfill UIII | |
| 03-18-06 Ran 208 jts 5-1/2" 17# P-110 LTC casing to 9100'. Cemented first stage with lead of 250 sx Interfill "H" (Den 11.9, yld 2.46) + 5 lb Gilsonite + 0.25 lb Flocele and tail of 200 sx Super (den 13.2, yld 1.61) + 0.5% | | | | |
| Lap-1 + 0.25 lb D-Air 3000 + 0.4% CFR-3 w/o Defoamer + 1 lb Salt + 5 lb Gilsonite + 0.25 lb Flocele + | | | | |
| 0.2% HR-7. | | | | |
| 03-19-06 Cemented second stage with lead of 640 sx Interfill C (den 11.9, yld 2.45) + 0.25 lb Flocele and tail of 150 | | | | |
| sx Premium H (den 15.6, yld 1.18). | | | | |
| 03-20-06 Released rig at 12 am. | | | | |
| 04-04-06 Tested casing to | 4000 psi for 30 minutes. | | | |
| 04-05-06 Ran CBL and found TOC at 2200'. | | | | |
| | | | | |
| | | | | |
| | | | # 1 | |
| | | | | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan. | | | | |
| SIGNATURE Datalut | TITLE | Regulatory Technician | DATE <u>April 12, 2006</u> | |
| Type or print name Natalie Krueger email address: nkrueger@cimarex.com Telephone No. 972-401-3111 For State Use Only | | | | |
| 10. State OSC OHLY | | | APR 1 8 2000 | |
| APPROVED BY: FOR RECORDS ONLYTTLE DATE Conditions of Approval (if any): | | | | |