State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen

Cabinet Secretary

Matthias Sayer

Deputy Cabinet Secretary

Heather Riley
Division Director

Response Required - Deadline Enclosed



Field Inspection Program
"Preserving the Integrity of Our Environment"

09-May-18

LONGFELLOW ENERGY, LP 16803 NORTH DALLAS PARKWAY ADDISON TX 75001

Dear Operator:

LETTER OF VIOLATION - Inspection

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO	N DETAIL	L SECTION		
Inspection Date Type Inspection D5/09/2018 Routine/Periodic Violations General Housekeeping (Rule 114)		odic	Inspector Tony Morales	Violation? Yes	H-20-17S-29E *Significant Non-Compliance? No	30-015-30919-00-0 Corrective Action Due By: 8/12/2018	Inspection No. iTM1812937746
	on Inspection:	OK. All Equipn 19.15.10.8 STA	nent and Location in	Good Shape ROX 20' X 50	. PJ STAINING ARO	OUND WELLHEAD+	
STATE 20 B No.004 Inspection Date Type Inspection		n	Inspector Violation?	H-20-17S-29E *Significant Non-Compliance?	30-015-30921-00-00 Corrective Action Due By: Inspection No.	O Inspection No.	
05/09/2018	Routine/Periodic Violations General Housekeeping (Rule 114)		Tony Morales	Yes	No		iTM1812938129
Comments of	n Inspection:		nent and Location in	Good Shape.	PJ STAINING ARC	OUND WELLHEAD	

G-20-17S-29E 30-015-30968-00-00 **STATE 20 B No.006** Corrective *Significant Inspection Inspection No. Violation? Inspector Non-Compliance? **Action Due By: Type Inspection** Date iTM1812935405 8/12/2018 Yes No Routine/Periodic **Tony Morales** 05/09/2018 Violations General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD **Comments on Inspection:** 19.15.10.8 B-20-17S-29E 30-015-31052-00-00 **STATE 20 B No.007** Corrective *Significant Inspection Inspection No. Violation? Inspector Non-Compliance? **Action Due By: Type Inspection** Date iTM1812939182 No 8/12/2018 05/09/2018 **Tony Morales** Yes Routine/Periodic Violations General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD **Comments on Inspection:** 19.15.10.8 O-17-17S-29E 30-015-31261-00-00 PHILLIPS 17 FEDERAL No.002 *Significant Corrective Inspection Inspection No. Inspector Violation? Non-Compliance? **Action Due By:** Type Inspection Date iTM1812940693 8/12/2018 No Yes **Tony Morales** 05/09/2018 Routine/Periodic **Violations** General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD **Comments on Inspection:** 19.15.10.8 30-015-31448-00-00 B-19-17S-29E PHILLIPS 19 FEDERAL No.007 Corrective *Significant Inspection Inspection No. Violation? **Action Due By:** Inspector Non-Compliance? **Type Inspection** Date iTM1812945974 8/12/2018 No **Tony Morales** Yes Routine/Periodic 05/09/2018 **Violations** General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD Comments on Inspection: 19.15.10.8 30-015-33070-00-00 G-20-17S-29E **STATE 20 B No.017** Corrective *Significant Inspection Inspection No. Violation? Non-Compliance? **Action Due By:** Inspector **Type Inspection** Date iTM1812935058 8/12/2018 Yes No 05/09/2018 Routine/Periodic **Tony Morales** Violations General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD **Comments on Inspection:** 19.15.10.8 30-015-33097-00-00 H-20-17S-29E **STATE 20 B No.015** *Significant Corrective Inspection Inspection No. Violation? Inspector Non-Compliance? **Action Due By: Type Inspection** Date 8/12/2018 iTM1812937967 **Tony Morales** Yes No Routine/Periodic 05/09/2018 Violations General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD Comments on Inspection: 19.15.10.8 30-015-33156-00-00 H-20-17S-29E **STATE 20 B No.016** Corrective *Significant Inspection Inspection No. Violation? Inspector Non-Compliance? **Action Due By: Type Inspection** Date 8/12/2018 iTM1812935551 No Yes Routine/Periodic Tony Morales 05/09/2018 **Violations** General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD **Comments on Inspection:** 19.15.10.8 CUSTOM WELDING HOBBS NM CRACK ON PJ.

STATE 20 B No.020

Inspection Date

Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

30-015-33205-00-00

Corrective Action Due By:

Inspection No.

05/09/2018

Routine/Periodic

Tony Morales

Yes

No

G-20-17S-29E

8/12/2018

iTM1812935291

Violations

General Housekeeping (Rule 114)

Comments on Inspection:

OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD

19.15.10.8

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.