State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen

Cabinet Secretary

Matthias Sayer

Deputy Cabinet Secretary

Heather Riley

Division Director



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

09-May-18

LONGFELLOW ENERGY, LP 16803 NORTH DALLAS PARKWAY ADDISON TX 75001

Dear Operator:

LETTER OF VIOLATION - Inspection

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

STATE 20 I Inspection Date 05/09/2018	Type Inspecti Routine/Per Violations		Inspector Tony Morales	Violation? Yes	H-20-17S-29E *Significant Non-Compliance? No	30-015-30919-00-0 Corrective Action Due By: 8/12/2018	Inspection No. iTM1812937746
Comments	on Inspection:	OK. All Equip	ment and Location in AINED AREA APPE	Good Shape.	PJ STAINING AR	OUND WELLHEAD+	
STATE 20 I	3 No.004				H-20-17S-29E	30-015-30921-00-0	0

INSPECTION DETAIL SECTION

7				H-20-17S-29E	30-015-30921-00-0		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
05/09/2018	Routine/Periodic	Tony Morales	Yes	No		iTM1812938129	

General Housekeeping (Rule 114)

Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD 19.15.10.8

STATE 20 B No.006 G-20-17S-29E 30-015-30968-00-00 Inspection *Significant Corrective Type Inspection Date Inspector Violation? Non-Compliance? Inspection No. **Action Due By:** 05/09/2018 Routine/Periodic Tony Morales Yes No 8/12/2018 iTM1812935405 **Violations** General Housekeeping (Rule 114) **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD 19.15.10.8 **STATE 20 B No.007** B-20-17S-29E 30-015-31052-00-00 Inspection *Significant Corrective Date **Type Inspection** Inspector Violation? Non-Compliance? Inspection No. **Action Due By:** 05/09/2018 Routine/Periodic **Tony Morales** Yes No 8/12/2018 iTM1812939182 **Violations** General Housekeeping (Rule 114) OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD **Comments on Inspection:** 19.15.10.8 PHILLIPS 17 FEDERAL No.002 O-17-17S-29E 30-015-31261-00-00 Inspection *Significant Corrective Date **Type Inspection** Inspector Violation? Non-Compliance? Action Due By: Inspection No. 05/09/2018 Routine/Periodic **Tony Morales** Yes No 8/12/2018 iTM1812940693 Violations General Housekeeping (Rule 114) **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD 19.15.10.8 PHILLIPS 19 FEDERAL No.007 B-19-17S-29E 30-015-31448-00-00 Inspection *Significant Corrective **Type Inspection** Date Inspector Violation? Non-Compliance? Inspection No. **Action Due By:** 05/09/2018 Routine/Periodic **Tony Morales** Yes No 8/12/2018 iTM1812945974 Violations General Housekeeping (Rule 114) Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD 19.15.10.8 **STATE 20 B No.017** G-20-17S-29E 30-015-33070-00-00 Inspection *Significant Corrective **Type Inspection** Date Inspector Violation? Non-Compliance? Inspection No. **Action Due By:** 05/09/2018 Routine/Periodic **Tony Morales** Yes No 8/12/2018 iTM1812935058 **Violations** General Housekeeping (Rule 114) **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD 19.15.10.8 **STATE 20 B No.015** H-20-17S-29E 30-015-33097-00-00 Inspection *Significant Corrective **Type Inspection** Date Inspector Violation? Non-Compliance? **Action Due By:** Inspection No. 05/09/2018 Routine/Periodic Tony Morales Yes No 8/12/2018 iTM1812937967 Violations General Housekeeping (Rule 114) Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD 19.15.10.8 **STATE 20 B No.016** H-20-17S-29E 30-015-33156-00-00 Inspection *Significant Corrective **Type Inspection** Date Inspector Violation? Non-Compliance? Inspection No. **Action Due By:** 05/09/2018 Routine/Periodic **Tony Morales** Yes No 8/12/2018 iTM1812935551 **Violations** General Housekeeping (Rule 114) **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD 19.15.10.8 CUSTOM WELDING HOBBS NM CRACK ON PJ.

STATE 20 B No.020

G-20-17S-29E

30-015-33205-00-00

Inspection

Date

Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

05/09/2018 Routine/Periodic

Tony Morales

Yes

No 8/12/2018 iTM1812935291

Violations

General Housekeeping (Rule 114)

Comments on Inspection:

OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD

19.15.10.8

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.