## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary Heather Riley Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

26-Apr-18

CFM OIL, LLC PO BOX 1176 ARTESIA NM 88210-8210

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			<b>INSPECTIO</b>	<b>V</b> DETAIL	SECTION		
GILLESPIE Inspection Date 04/25/2018	STATE No.00 Type Inspection Routine/Period		Inspector Tony Morales	Violation? Yes	A-27-17S-28E *Significant Non-Compliance? No	<b>30-015-01588-00-0</b> Corrective Action Due By: 7/29/2018	0 Inspection No. iTM1811550800
Comments o	Violations General Housekee on Inspection:	ping (Rule 114) OK. All Equipm 19.15.10.8	ent and Location in	Good Shape	. PJ STAINING AR	OUND WELLHEAD	
GILLESPIE STATE No.001					D-27-17S-28E *Significant	30-015-21785-00-0 Corrective	
Inspection Date 04/25/2018	Type Inspection Routine/Periodic		Inspector Tony Morales	Violation? Yes	Non-Compliance? No	<b>Action Due By:</b> 7/29/2018	Inspection No. iTM1811542784
	General Houseke	eping (Rule 114)				NETED STAINING	
Comments	on Inspection:	OK. All Equipm AROUND WEI	ent and Location in LHEAD / OTHER	n Good Shape R DEBRIS 19	e. PJ NO ELECTRIC .15.10.8	CMETER STAINING	

GILLESPIE Inspection	C STATE No.003 Type Inspection Routine/Periodic		Tecnostor	Violation? Yes	D-27-17S-28E *Significant Non-Compliance? No	<b>30-015-21903-00-00</b> Corrective Action Due By: 7/29/2018 i	) Inspection No. iTM1811542156
Date			Inspector Tony Morales				
04/25/2018							
	Violations						
	General Housekee	ping (Rule 114)					
<b>Comments</b>	on Inspection:	OK. All Equipt 19.15.10.8	nent and Location ir	Good Shape	. PJ OLD PJ / DEBI	RIS ON LOCATION	
GILLESPIE STATE No.007					C-27-17S-28E	30-015-22497-00-00	
Inspection Date	Type Inspection Routine/Periodic		Inspector Tony Morales	Violation? Yes	*Significant Non-Compliance? No	<b>Corrective</b> <b>Action Due By:</b> 7/29/2018	Inspection No. iTM1811548894
04/25/2018							
	Violations						
	General Houseke	eping (Rule 114)					
Comments on Inspection: Idle Well (Rule Shape. PJ NO OLD PJ ON L			e 201) ???? ) ELECTRICAL MC OCATION 19.15.1(	DTOR ON PJ	OK. All Equipment and Location in Good OLD UNMARKED 55 GALLON DRUMS		

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.