

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUN 18 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division DISTRICT IV-ARTESIA O.G.B.
1220 South St. Francis Dr.
Santa Fe, NM 87505
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1817236303 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company: XTO Energy **BOPCO 2100737** Contact: Amy C. Ruth

Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No: 575-689-3380

Facility Name: PLU Pierce Canyon 17 Federal 1H Battery Facility Type: Exploration and Production
(API for PLU CVX JV PC #001H)




Surface Owner: Federal Mineral Owner: Federal API No: 30-015-36635

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	25S	30E	480	South	290	East	Eddy

Latitude 32.124290° Longitude -103.895694° NAD83

NATURE OF RELEASE

Type of Release	Fire/lightning strike	Volume of Release	0	Volume Recovered	0
Source of Release	Enardo valve	Date and Hour of Occurrence	6/3/2018 10:30 pm	Date and Hour of Discovery	6/3/2018 10:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Crystal Weaver (NMOCD), Shelly Tucker/Jim Amos (BLM)		
By Whom?	Kyle Littrell	Date and Hour:	6/5/2018 11:31 am by email		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Lightning struck near the battery and caused a fire from a relief (enardo) valve on top of the tank battery. Production was shut in to extinguish the fire.					
Describe Area Affected and Cleanup Action Taken.* No fluids or fire impacted the pad surface or containment.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Amy C. Ruth		Signed By:  Approved by Environmental Specialist:			
Title: Environmental Coordinator		Approval Date: 6/19/18		Expiration Date: N/A	
E-mail Address: Amy_Ruth@xtoenergy.com		Conditions of Approval:		Attached: 	
Date: 6/18/2018 Phone: 575-689-3380		FINAL			

* Attach Additional Sheets If Necessary