

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM118108

Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other8. Well Name and No.
HH SO 8 P2 14H

2. Name of Operator

CHEVRON USA INCORPORATED

Contact: LAURA BECERRA

E-Mail: LBECERRA@CHEVRON.COM

9. API Well No.

30-015-43931-00-X1

3a. Address

6301 DEAUVILLE BLVD
MIDLAND, TX 79706

3b. Phone No. (include area code)

Ph: 432-687-7665

10. Field and Pool or Exploratory Area
WILDCAT

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 17 T26S R27E NWNW 330FNL 960FWL

11. County or Parish, State

EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐
- Notice of Intent
-
- ☒
- Subsequent Report
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- | | | | |
|---|---|--|---|
| <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Hydraulic Fracturing | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input checked="" type="checkbox"/> Other |
| <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | Drilling Operations |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Drilling Activities Report:

7/31/17 - 8/9/17 - Drill 12 ?? Intermediate hole from to 8,995?
8/10/17 ? Run 9 5/8" 43.5# HCL-80 LTC casing and set @ 8,981? cement in place.
8/11/17 ? Lead w/CL C 1,132 sacks, Yield: 2.45/sack, Dens: 11.90#/gal and Tail: CL H 290 sacks,
Yield: 1.20/sack, Dens: 15.60#/gal with DV Tool @ 2,046? centralized the bottom joints with 1 bow
spring every 3 joints to surface (72 total).
Float collar @ 8,893?, Float shoe @ 8,981?. Full returns with 6 bbls cement to surface. WOC >5 hrs
per BLM time requirement prior to pressure test. Held 3,100 psi for 30 min
8/12/17 - Test casing to 3,100 psi for 30 min, test good.

8/12/17-8/29/17 - Drill 8 ?? casing hole to 10,683?

CC 6-29-18
Accepted for record - NMOCDNM OIL CONSERVATION
ARTESIA DISTRICT

JUN 27 2018

RECEIVED

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #402391 verified by the BLM Well Information System
For CHEVRON USA INCORPORATED, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 01/26/2018 (18PP0891SE)

Name (Printed/Typed) LAURA BECERRA

Title PERMITTING SPECIALIST

Signature (Electronic Submission)

Date 01/26/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

ACCEPTED

JONATHON SHEPARD
Title PETROLEUM ENGINEER

Date 06/13/2018

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #402391 that would not fit on the form

32. Additional remarks, continued

8/30/17 - Run 7 5/8" 29.70# P-110 TSH 513 liner @ 10,200'. Float collar @ 10,112', Float shoe @ 10,200'.

8/31/2017 - Cement in place, CL H, 152 sacks, Yield: 1.19/sack, Dens: 15.60#/gal. Full returns throughout job. WOC >5 hrs per BLM time requirement prior to pressure test.

9/1/17-9/20/17 - Held 1,445 psi for 30 min. Drilled 6" Production hole to 20,474'.

9/21/17 ? Cleanup and full BOPE test, good test.

9/22/17 ? Run 5" 20# P-110 BTC casing and set at 9,388'.

9/23/17 ? Run 5" 18.00# P-110 TSH521 casing and set at 20,445'.

9/24/17 ? Cement casing in place. Tail: CL H 2,464 sacks, Yield: 1.20/sack, Dens: 15.60#/gal centralized the bottom joints with 1 bow spring every 3 joints to surface (153 total). Float collar @ 20,401', Float shoe @ 20,445'.

9/26/17 ? Nipped up temporary blanking cap with pressure gauge. Tested to 10,000 psi for 10K wellhead, test good.

Revisions to Operator-Submitted EC Data for Sundry Notice #402391

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	DRG SR	DRG SR
Lease:	NMNM118108	NMNM118108
Agreement:		
Operator:	CHEVRON U.S.A. 6301 DEAUVILLE BLVD. MIDLAND, TX 79706 Ph: 432-687-7665	CHEVRON USA INCORPORATED 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432 687 7100
Admin Contact:	LAURA BECERRA PERMITTING SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665	LAURA BECERRA PERMITTING SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665
Tech Contact:	LAURA BECERRA PERMITTING SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665	LAURA BECERRA PERMITTING SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665
Location:		
State:	NM	NM
County:	EDDY	EDDY
Field/Pool:	WOLFCAMP (GAS)	WILDCAT
Well/Facility:	HH SO 8 P2 14H Sec 17 T26S R27E Mer NMP 330FNL 960FWL	HH SO 8 P2 14H Sec 17 T26S R27E NWNW 330FNL 960FWL