Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIPRATISDAD FIELD BUREAU OF LAND MANAGEMENT AND MANAGEMENT A **UNITED STATES**

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter to the state of the state

abandoned well. Use form 3160-3 (APD) for such proposals.					, ,		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well  Oil Well Gas Well Oth			8. Well Name and No. HH SO 8 P2 6H				
2. Name of Operator CHEVRON USA INCORPORA	ERRA COM		9. API Well No. 30-015-43934-00-X1				
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706	3b. Phone No. (include area code) Ph: 432-687-7665			10. Field and Pool or Exploratory Area WILDCAT			
4. Location of Well (Footage, Sec., T.			11. County or Parish, State				
Sec 17 T26S R27E NWNW 280FNL 960FWL					EDDY COUNTY, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICAT	ΓE NATURE OI	F NOTICE,	REPORT, OR OTH	ER I	DATA
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	☐ Acidize	☐ Deep	en	☐ Producti	on (Start/Resume)	۱ 🔾	Water Shut-Off
_	☐ Alter Casing	☐ Hydi	raulic Fracturing	☐ Reclamation		<b>a</b> /	Well Integrity
Subsequent Report     ■	☑ Subsequent Report ☐ Casing Repair		■ New Construction		ecomplete		Other  Orilling Operations
☐ Final Abandonment Notice	□ Change Plans		and Abandon	☐ Tempor	arily Abandon	ווט	ining Operations
	☐ Convert to Injection	Plug	Back	☐ Water D	isposal		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi	rk will be performed or provide l operations. If the operation re- pandonment Notices must be fil	the Bond No. on sults in a multiple ed only after all i	ifile with BLM/BIA e completion or reco requirements, includi	. Required sub mpletion in a r ing reclamation	sequent reports must be t new interval, a Form 3160	filed w )-4 mu	of thin 30 days  ast be filed once
determined that the site is ready for final inspection.  Drilling activities details:  Accepted for record - NMOCD							
7/03/2017 - Drill 12 1/4? Intermediate hole T/9,005?. 7/14/2017- Run 9 5/8? 43.5# HCL-80 LTC casing and set @ 8,993? cement in place Lead w/CL C 1,139 sacks, Yield: 2.45/sack, Dens: 11.90#/gal and Tail: CL H 290 sacks, Yield: 1.20/sack, Dens: 15.60#/gal with DV Tool @ 2,083? centralized the bottom joints with 1 bow sp every 3 joints to surface (72 total). Float collar @ 8,907?, Float shoe @ 8,993?. Full returns to surface. held 2,985 psi for 30 min					ring JUN 2 7 2018		
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #401515 verified by the BLM Well Information System  For CHEVRON USA INCORPORATED, sent to the Carlsbad  Committed to AFMSS for processing by PRISCILLA PEREZ on 01/25/2018 (18PP0822SE)							
Name (Printed/Typed) LAURA BECERRA			Title PERMITTING SPECIALIST				
Signature (Electronic Submission)			Date 01/18/2018				
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By ACCEPTED			JONATHO TitlePETROLE	N SHEPAR UM ENGINI			Date 06/13/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe s to any matter w	rson knowingly and ithin its jurisdiction.	willfully to ma	ake to any department or	agency	y of the United

## Additional data for EC transaction #401515 that would not fit on the form

## 32. Additional remarks, continued

12/1/2017 ? Lead w/CL H 3,228 sacks, Yield: 1.20/sack, Dens: 15.60#/gal and Tail: CL H 100 sacks, Yield: 1.90/sack, Dens: 16.0#/gal centralized the bottom joints with 1 bow spring every 3 joints to surface (156 total). Float collar @ 20,150?, Float shoe @ 20,192?. Full returns to surface. Tested to 10,000 psi for 15 min, good test.

Copy of wellbore schematic attached.

## Revisions to Operator-Submitted EC Data for Sundry Notice #401515

**Operator Submitted** 

**BLM Revised (AFMSS)** 

Sundry Type:

DRG SR

NMNM118108

DRG SR

NMNM118108

Agreement:

Operator:

Lease:

CHEVRON U.S.A. 6301 DEAUVILLE BLVD. MIDLAND, TX 79706 Ph: 432-687-7665

CHEVRON USA INCORPORATED 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432 687 7100

Admin Contact:

LAURA BECERRA PERMITTING SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

LAURA BECERRA PERMITTING SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665

**Tech Contact:** 

LAURA BECERRA PERMITTING SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

LAURA BECERRA
PERMITTING SPECIALIST
E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

Location:

State: County: NM

**EDDY** 

NM EDDY

Field/Pool:

**WOLFCAMP** 

WILDCAT

Well/Facility:

HH SO 8 P2 6H

Sec 17 T26S R27E Mer NMP NWNW 280FNL 960FWL

HH SO 8 P2 6H

Sec 17 T26S R27E NWNW 280FNL 960FWL