

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**NAB1822056547** **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company: Cimarex Energy Co. of Colorado	Contact: Gloria Garza
Address: 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-234-3204
Facility Name: Intrepid 3 Federal Com 1H	Facility Type: Battery
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-38979	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	3	19S	30E	250	N	330	W	Eddy

Latitude 32.696127 Longitude -103.965637

### NATURE OF RELEASE

Type of Release : Produced Water	Volume : 35 BBLs	Volume Recovered: 35 BBLs
Source of Release : Battery/Fire Tube	Date and Hour of Occurrence: 7/21/2018 12:15 PM	Date and Hour of Discovery: 7/21/2018 12:15 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Shelly Tucker	
By Whom? Gloria Garza	Date and Hour: 7/22/2018 9:46 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The fire tube inside of the heater treater developed a leak due to corrosion. The fire tube has been replaced and put back into service.

Describe Area Affected and Cleanup Action Taken.\*

All fluids released were contained inside of the lined containment. We recovered all fluids and power washed the containment. Christine Alderman inspected the containment on August 1, 2018 and found the containment to be intact and able to hold fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: <i>Gloria Garza</i>	Approved by Environmental Specialist: <i>Maria Pruett</i>	
Printed Name: Gloria Garza	Approval Date: 08/07/18	Expiration Date: N/A
Title: ESH Specialist	Conditions of Approval: Like as BLM	
E-mail Address: ggarza@cimarex.com	Attached <input checked="" type="checkbox"/> <i>4899</i>	
Date: 8.6.2018	Phone: 432-234-3204	

\* Attach Additional Sheets If Necessary

FINAL