
tSubmit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		30-015-42307
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			5. Indicate Type of Lease STATE FEE
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No. VB-1659
SUNDRY NO	TICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
OD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (**IMMONDICONSERVATION PROPOSALS.) ARTESIA DISTRICT 8 Well Number 4			
1. Type of Well: Oil Well	Gas Well Other	IA DISTRICT	8. Well Number 1
2. Name of Operator Caza Oil and Gas, Inc	AUG	2 1 2018	9. OGRID Number 249099
3. Address of Operator 200 N. Lorraine St #1550.,	Midland TX 79701 RE	CEIVED	10. Pool name or Wildcat Cass Draw; Delaware 10410
4. Well Location C 660 south 1980 east			
Onit Letter			
Section 22	Township 23S Ra 11. Elevation (Show whether DR	ange 27E	NMPM County Eddy
3158' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING [DOWNHOLE COMMINGLE [MULTIPLE COMPL	CASING/CEMEN	I JOB
	<u></u>		
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
An MIT was performed on the well. The chart is attached. A CIPB was placed at 2215'MD and 50' of cement placed above the CIPB. The detailed WBS is attached.			
Caza requests to have the well put in to TA status for a period of 2 years.			
		Tes	restry Associated States Corporate
		val.	8-21-2020
		•	
Spud Date: 04/30/201	A Rig Release D	ate: 06/09/	2014
3944 Date. 04/30/201	Kig Keleuse D	00/03/	2014
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereby certify that the information above is true and complete to the best of my knowledge and benefit			
SIGNATURE TITLE Contract Engineer DATE 08/21/2018			
Type or print name Steve M	Orris E-mail addres	steve.morris@n	nojoenergy.com PHONE: 403-923-9750
For State Use Only			
	TITLE S/A	_	DATE 8-21-18

NM OIL CONSERVATION ARTESIA DISTRICT

AUG 21 2018


RECEIVED



Forehand Ranch 22 St # 1

Location: SW/SE Section 22_T23S_R27E_Eddy County, New Mexico





State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary NM OIL CONSERVATION Butther Riley, Division Director ARTESIA DISTRICT OII Conservation Division

Matthias Sayer Deputy Cabinet

AUG 21 2018



RECEIVED

Date 8-17-18 API#30-0/5-42307

Dear Operator:

I have this date performed a Mechanical Integrity Test on the Forehand If this test was successful the original chart has been retained by the operator. Send a legible scan of the chart with form C-103 indicating reason for test. It will be scanned into the well file in 7 to 10 days (pending receipt of legible scan and form C-103). The well files are located at www.emnrd.state.nm.us/ocd/0CD0nline.htm If this test was unsuccessful the original chart has been returned to the operator pending repair and retest of the well, which must be accomplished within 90 days. If this is a test of a repaired well, previously in non-compliance, all dates and requirements of the original non-compliance are still in effect. No expectation of extension should be construed because of this test. If this test was for Temporary Abandonment include in your detailed description, on Form C-103, the location of the CIBP and any other tubular goods in the well, as well as your request for TA status. Include how long you are requesting the TA status for. If this is a successful test of a repaired well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a detailed description of the repair to the well. Only after receipt of the C-103 will the non-compliance be closed. If this is a successful Initial Test of an injection well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a detailed description of the work done on this well including the position of the packer, tubing information, the date of first injection, the tubing pressure and Injection volume. Contact Rusty Klein at 575-748-1283 x109 to verify all required paperwork has been received before you can begin injection. If I can be of additional service contact me at (575) 748-1283 Ext 114.

Thank You.

Gilbert Cordero Staff Manager District II - Artesia