## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer

**Deputy Cabinet Secretary** 

Heather Riley
Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

10-Sep-18

## **BREITBURN OPERATING LP**

1111 Bagby Street Suite 1600 Houston TX 77002-7002

**LETTER OF VIOLATION - Inspection** 

## Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO!	V DETAIL	L SECTION		
ARTESIA UNIT No.028 Inspection Date Type Inspection  09/10/2018 Routine/Periodic			Inspector Gilbert Cordero	Violation? Yes	M-35-17S-28E *Significant Non-Compliance?	30-015-01732-00- Corrective Action Due By: 12/14/2018	00 Inspection No. iGC1825349270
	on Inspection:	Well Sign (Rule		ATOR NAM		ORRECTED (QUANT	
ARTESIA UNIT No.029 Inspection Date Type Inspection		Inspector	Violation?	N-35-17S-28E *Significant Non-Compliance?	30-015-01742-00- Corrective Action Due By:	00 Inspection No.	
09/10/2018	Routine/Period	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825348916
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	ME NEEDS TO BE CO	ORRECTED (QUANT	TUM
ARTESIA UNIT No.022 Inspection Date Type Inspection		Inspector	Violation?	K-35-17S-28E *Significant Non-Compliance?	30-015-01747-00- Corrective Action Due By:	DO  Inspection No.	
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825348613
Comments	on Inspection:	• •	19.15.16.8). OPER SIGN IS NOT LEGI		ME NEEDS TO BE CO	ORRECTED (QUAN	ГUМ

F-35-17S-28E ARTESIA UNIT No.013 30-015-01754-00-00 \*Significant Corrective Inspection Inspection No. Non-Compliance? Type Inspection Inspector Violation? Action Due By: Date iGC1825337209 Gilbert Cordero Yes No 12/14/2018 09/10/2018 Routine/Periodic Well Sign (Rule 19.15.16.8). OPERATOR NAME NEEDS TO BE CORRECTED (QUANTUM Comments on Inspection: RESOURCES) **ARTESIA UNIT No.014** G-35-17S-28E 30-015-01755-00-00 Inspection \*Significant Corrective Violation? Inspection No. Type Inspection Inspector Action Due By: Non-Compliance? iGC1825336729 No 12/14/2018 09/10/2018 Routine/Periodic Gilbert Cordero Yes Well Sign (Rule 19.15.16.8). OPERATOR NAME NEEDS TO BE CORRECTED Comments on Inspection: E-35-17S-28E 30-015-29862-00-00 ARTESIA UNIT No.071 \*Significant Corrective Inspection Inspection No. Violation? Type Inspection Inspector Non-Compliance? Action Due By: Date iGC1825338652 12/14/2018 Gilbert Cordero 09/10/2018 Routine/Periodic Yes No Well Sign (Rule 19.15.16.8). OPERATOR NAME NEEDS TO BE CORRECTED (SBX Comments on Inspection: RESOURCES) E-35-17S-28E 30-015-29863-00-00 **ARTESIA UNIT No.072** \*Significant Corrective Inspection Violation? Inspection No. Type Inspection Inspector Action Due By: Date Non-Compliance? iGC1825339061 09/10/2018 Routine/Periodic Gilbert Cordero Yes No 12/14/2018 Well Sign (Rule 19.15.16.8). OPERATOR NAME NEEDS TO BE CORRECTED (QUANTUM Comments on Inspection: RESOURCES) F-35-17S-28E 30-015-29999-00-00 ARTESIA UNIT No.075 \*Significant Corrective Inspection Inspection No. Violation? Inspector Date Type Inspection Non-Compliance? Action Due By: Gilbert Cordero Yes No 12/14/2018 iGC1825337749 Routine/Periodic 09/10/2018 Well Sign (Rule 19.15.16.8). OPERATOR NAME NEEDS TO BE CORRECTED (QUANTUM Comments on Inspection: RESOURCES) K-35-17S-28E 30-015-31488-00-00 ARTESIA UNIT No.088 \*Significant Corrective Inspection Type Inspection Inspector Violation? Non-Compliance? Action Due By: Inspection No. Date iGC1825348358 Gilbert Cordero Yes 12/14/2018 09/10/2018 Routine/Periodic Well Sign (Rule 19.15.16.8). OPERATOR NAME NEEDS TO BE CORRECTED (QUANTUM Comments on Inspection: RESOURCES) M-35-17S-28E 30-015-33285-00-00 ARTESIA UNIT No.101 \*Significant Corrective Inspection Inspection No. Inspector Violation? Type Inspection **Action Due By:** Non-Compliance? Date 12/14/2018 iGC1825349099 09/10/2018 Routine/Periodic Gilbert Cordero Yes No Well Sign (Rule 19.15.16.8). OPERATOR NAME NEEDS TO BE CORRECTED (QUANTUM Comments on Inspection: RESOURCES)

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Gilbert

Staff Mor

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.