## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary.

**Matthias Sayer** 

**Deputy Cabinet Secretary** 

**Heather Riley Division Director** 





## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

10-Sep-18

## BREITBURN OPERATING LP

1111 Bagby Street Suite 1600 Houston TX 77002-7002

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTION	V DETAIL	SECTION		
ARTESIA UNIT No.028 Inspection Date Type Inspection		1	Inspector	Violation?	M-35-17S-28E *Significant Non-Compliance?	30-015-01732-00-0 Corrective Action Due By:	O Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825349270
Comments	on Inspection:	• •	19.15.16.8). OPER SIGN IS NOT LEG		1E NEEDS TO BE CO	ORRECTED (QUANT	UM
ARTESIA U	JNIT No.029  Type Inspection	ı	Inspector	Violation?	N-35-17S-28E *Significant Non-Compliance?	30-015-01742-00-0 Corrective Action Due By:	() Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825348916
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	ME NEEDS TO BE CO	ORRECTED (QUANT	UM
ARTESIA U Inspection Date	JNIT No.022  Type Inspection	1	Inspector	Violation?	K-35-17S-28E *Significant Non-Compliance?	30-015-01747-00-0 Corrective Action Due By:	O Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825348613
Comments	on Inspection:		19.15.16.8). OPER SIGN IS NOT LEGI		ME NEEDS TO BE CO	ORRECTED (QUANT	ÜМ

ARTESIA U Inspection Date	NIT No.013  Type Inspection		Inspector	Violation?	F-35-17S-28E *Significant Non-Compliance?	30-015-01754-00-0 Corrective Action Due By:	00 Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825337209
Comments of	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	ME NEEDS TO BE CO	ORRECTED (QUANT	TUM .
ARTESIA U	NIT No.014  Type Inspection		Inspector	Violation?	G-35-17S-28E *Significant Non-Compliance?	30-015-01755-00-0 Corrective Action Due By:	00 Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825336729
Comments of	on Inspection:	Well Sign (Rule	19.15.16.8). OPER	ATOR NAM	ME NEEDS TO BE CO	ORRECTED	
ARTESIA UNIT No.071 Inspection			Inspector	Violation?	E-35-17S-28E *Significant	30-015-29862-00-0 Corrective	00 Inspection No.
Date 09/10/2018	Type Inspection Routine/Perio		Gilbert Cordero	Yes	Non-Compliance? No	Action Due By: 12/14/2018	iGC1825338652
	on Inspection:				1E NEEDS TO BE C		1001623336032
ARTESIA U Inspection Date	JNIT No.072  Type Inspection	1	Inspector	Violation?	E-35-17S-28E *Significant Non-Compliance?	30-015-29863-00-0 Corrective Action Due By:	00 Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825339061
Comments of	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	ME NEEDS TO BE C	ORRECTED (QUANT	ГUМ
ARTESIA U	JNIT No.075	1	Inspector	Violation?	F-35-17S-28E *Significant Non-Compliance?	30-015-29999-00-0 Corrective Action Due By:	00 Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825337749
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAN	ME NEEDS TO BE C	ORRECTED (QUANT	ГИМ
ARTESIA UNIT No.088 Inspection		Inspector Violation?		K-35-17S-28E *Significant	30-015-31488-00-00  Corrective Action Due Ry: Inspection No.		
Date 09/10/2018	Type Inspection Routine/Perio		Inspector Gilbert Cordero	Yes	Non-Compliance? No	Action Due By: 12/14/2018	iGC1825348358
	on Inspection:					ORRECTED (QUANT	
ARTESIA UNIT No.101 Inspection		Incorptor	Violetia-2	M-35-17S-28E *Significant	30-015-33285-00- Corrective		
Date Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.	
09/10/2018 Comments	Routine/Perio	,	Gilbert Cordero 19.15.16.8). OPER	Yes ATOR NAM	No ME NEEDS TO BE C	12/14/2018 ORRECTED (QUANT	iGC1825349099 гим

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Staff Mgr

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.