## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

**Matthias Sayer** Deputy Cabinet Secretary Heather Riley Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

10-Sep-18

## **BREITBURN OPERATING LP**

1111 Bagby Street Suite 1600 Houston TX 77002-7002

## **LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		1	NSPECTION	DETAIL	SECTION		
ARTESIA U Inspection Date	NIT No.028 Type Inspection	Ins	spector	Violation?	M-35-17S-28E *Significant Non-Compliance?	30-015-01732-00-00 Corrective Action Due By:	Inspection No.
09/10/2018	Routine/Period	lic Gi	ilbert Cordero	Yes	No	12/14/2018	iGC1825349270
Comments o	on Inspection:	Well Sign (Rule 19. RESOURCES) SIG			IE NEEDS TO BE CO	ORRECTED (QUANTU	J <b>M</b>
ARTESIA U Inspection Date	UNIT No.029 Type Inspection	Ins	spector	Violation?	N-35-17S-28E *Significant Non-Compliance?	30-015-01742-00-00 Corrective Action Due By:	Inspection No.
09/10/2018	Routine/Period	lic Gi	ilbert Cordero	Yes	No	12/14/2018	iGC1825348916
Comments o	on Inspection:	Well Sign (Rule 19. RESOURCES)	15.16.8). OPERA	TOR NAM	IE NEEDS TO BE CO	ORRECTED (QUANTL	JM
ARTESIA U Inspection Date	NIT No.022 Type Inspection	Īn	spector	Violation?	K-35-17S-28E *Significant Non-Compliance?	30-015-01747-00-0( Corrective Action Due By:	Inspection No.
09/10/2018	Routine/Period	tic Gi	ilbert Cordero	Yes	No	12/14/2018	iGC1825348613
Comments of	on Inspection:	Well Sign (Rule 19. RESOURCES) SIG	,		IE NEEDS TO BE CO	ORRECTED (QUANTU	JM
							4
		Oil Conservation	Division * 811 S.	First St. * A	rtesia, New Mexico 882	210	

Phone: 575-748-1283 \* Fax: 575-748-9720 \* http://www.emnrd.state.nm.us

ARTESIA U Inspection Date	NIT No.013 Type Inspection		Inspector	Violation?	F-35-17S-28E *Significant Non-Compliance?	30-015-01754-00-0 Corrective Action Due By:	0 Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825337209
Comments o	n Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	IE NEEDS TO BE CO	ORRECTED (QUANT	U <b>M</b>
ARTESIA U Inspection					G-35-17S-28E *Significant	<b>30-015-01755-00-0</b> Corrective	
Date	Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
09/10/2018	Routine/Perio		Gilbert Cordero	Yes	No	12/14/2018	iGC1825336729
Comments o	n Inspection:	Well Sign (Rule	19.15.16.8). OPER	ATOR NAM	IE NEEDS TO BE CO	ORRECTED	
ARTESIA UNIT No.071 Inspection				¥/:-1-4:9	E-35-17S-28E *Significant	30-015-29862-00-0 Corrective	0 Inspection No.
Date	Type Inspectior		Inspector	Violation?	Non-Compliance?	Action Due By:	•
09/10/2018	Routine/Perio		Gilbert Cordero	Yes	No	12/14/2018	iGC1825338652
Comments o	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	1E NEEDS TO BE C	ORRECTED (SBX	
ARTESIA U Inspection Date	NIT No.072		Inspector	Violation?	E-35-17S-28E *Significant Non-Compliance?	<b>30-015-29863-00-0</b> Corrective Action Due By:	0 Inspection No.
09/10/2018	Routine/Perio		Gilbert Cordero	Yes	No	12/14/2018	iGC1825339061
	on Inspection:					ORRECTED (QUANT	
ARTESIA U			<b>.</b> .		F-35-17S-28E *Significant	30-015-29999-00-0 Corrective	-
Date	Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
09/10/2018 Comments o	Routine/Peric on Inspection:		Gilbert Cordero 19.15.16.8). OPER	Yes ATOR NAM	No 1E NEEDS TO BE C	12/14/2018 ORRECTED (QUANT	iGC1825337749 UM
Inspection	JNIT No.088		•	5/1-1-419	K-35-17S-28E *Significant	30-015-31488-00-0 Corrective	0 Inspection No.
Date	Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	•
09/10/2018	Routine/Peric		Gilbert Cordero	Yes	No	12/14/2018	iGC1825348358
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	AE NEEDS TO BE C	ORRECTED (QUANT	UM
ARTESIA UNIT No.101 Inspection					M-35-17S-28E *Significant	30-015-33285-00-0 Corrective	0
Date	Type Inspection	n	Inspector	Violation?	Non-Compliance?		Inspection No.
09/10/2018	Routine/Peric		Gilbert Cordero	Yes	No	12/14/2018	iGC1825349099
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	RATOR NAM	ME NEEDS TO BE C	ORRECTED (QUANT	ŬΜ

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, gilbert ( Staff Mgr

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

> Oil Conservation Division \* 811 S. First St. \* Artesia, New Mexico 88210 Phone: 575-748-1283 \* Fax: 575-748-9720 \* http://www.emnrd.state.nm.us