Form 3160-5, (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT CATISDAD FIELD 5 CANADA No. 15 C

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter (a)

abandoned wei	II. Use form 3160-3 (APD) for such p	proposals.	AIFIC	So df Indian, Allottee or	Tribe Name			
SUBMIT IN T	TRIPLICATE - Other instr	ructions on	page 2		7. If Unit or CA/Agree NMNM114177	ment, Name and/or No.			
Type of Well Oil Well	ner		· ·		8. Well Name and No. NILE STATE 22 C	OM 2H			
2. Name of Operator LEGACY RESERVES OPERA	Contact: C	JOHN SAEN acylp.com	Z		9. API Well No. 30-015-34422-00	D-S1			
3a. Address		3b. Phone No Ph: 432-68	o. (include area code)		10. Field and Pool or E	xploratory Area H - WOLFCAMP			
MIDLAND, TX 79702									
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)				11. County or Parish, State				
Sec 22 T17S R24E SWSW 96	60FSL 760FWL				EDDY COUNTY	, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA			
TYPE OF SUBMISSION			TYPE OF	ACTION					
Notice of Intent ■ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Producti	ion (Start/Resume)	■ Water Shut-Off			
_	☐ Alter Casing	□ Нус	Iraulic Fracturing	☐ Reclama	ation	■ Well Integrity			
☐ Subsequent Report	□ Nev	v Construction	☐ Recomp	lete	Other				
☐ Final Abandonment Notice	□ Change Plans	Plu;	g and Abandon	▼ Tempore	arily Abandon				
	☐ Convert to Injection	☐ Plu	g Back	☐ Water D	Disposal				
determined that the site is ready for fi Attached please find the write Shepard-BLM request.		g cement plu	g information per	Jonathon	RECEIVE)			
	Accepted for	9-17- 	/8 MOCD		SEP 1 4 2	2018			
	Accepted los				DIST RICT II-ARTES	SIA O.C.D.			
14. 1 hereby certify that the foregoing is Com Name (Printed/Typed) JOHN SA	Electronic Submission #4 For LEGACY RESE mitted to AFMSS for proce	RVES OPER	ATING LP, sent to SCILLA PEREZ or	o the Carlsba	nd (18PP2488SE)				
Signature (Electronic S	Submission)	· · · · · · · · · · · · · · · · · · ·	Date 08/17/2	018	·				
	THIS SPACE FO	R FEDERA	AL OR STATE	OFFICE U	SE				
Approved By /S.	/ Jonathon Shepa	TitPetrol	SEP 1 1 2018						
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the applicant to conduct the applicant the applic	itable title to those rights in the	not warrant or subject lease	1 -		ld Office				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ake to any department or	agency of the United			

Legacy Reserves

DAILY OPERATIONS REPORT

NILE 22 ST COM OIL # 2H

Printed Aug 17, 2018 Page 1 of 1

NILE 22 ST COM OIL #2H

EDDY Co., NM

BOLO ID: 300251.02

Zone:

TA Well

May 24, 2016 Tuesday

(Day 1)

SICP- 000#. SITP- 000#.

Move pulling unit to location. Remove barrier around well.

Daily Cost:

\$1,000

Cum. Cost:

\$1,000

May 25, 2016 Wednesday

(Day 2)

SIP- 000#.

Nipple down well head and nipple up blow out preventer. Pull out of hole and stand back 71 stands 2 3/8" Tubing(grade unknown). Move in rig up wireline. Run in hole with 5 1/2" Cast Iron Bridge Plug. Set plug at 4500' and make two more runs dumping 35' cement on plug. Casing had no fluid. Rig down move out wireline.

Run in hole with production tubing and circulate well with 100bbls packer fluid. Pull out of hole and lay down 142 joints 2 3/8" production tubing. Top off casing with packer fluid. Nipple down blow out preventer and nipple up well head with hanger. Rig down move out pulling unit.

Test and chart casing at 580# for thirty minutes with no loss of pressure. Secured well.

Notified production of joint count and that job was complete.

Daily Cost:

\$8,700

Cum. Cost:

\$9,700

Well Service Report NILE 22 ST COM OIL # 2H

Printed: 8/17/2018

BOLO ID: 300251.02 API # 3001534422

Event Date	5/24/2016	6 Classification 880-LOE				Downtime & Latest Well Te			ell Test	
Fail Date	5/24/2016	Category SubSurface		AFE		Prod. Off	5/24/2016	12:00 am	Oil	0.0
Start Date	5/24/2016	Reason	TA	Frmn	Manual Sorian	Prod. On	5/25/2016	11:59 pm	Gas	0.0
End Date	5/25/2016	Status	Complete	Beat	Thames Sout	Days Off	2.0	0	Wtr	0.0
Service Co SWABCO, Inc. Failure Review				V	Failed Item	d Item Brand				
Yard Type Failure				Failed Part Coating						
Unit # Failure Cause 1				Size / Grad Area Failed						
Operator	Ivan R.	R. Failure Cause 2			Description	Failure Depth				
Hrs.		<u> </u>					Updated	Nov 30, 2	016 3:09 p	m_

Overview

TA Well

Cost (All Days)

Expense Item	Cost
BOP	500
Pulling Unit	2,000
Pump Truck	1,600
Vacuum Truck	1,100
Wireline	4,500

Total Cost \$9,700

Tubing

Tubing									Date Ran: 5/25/2016			
Description	# Items	Length	OD Wt.	Grade	Joint-Thd	Class	Coating	I D	Drift ID	Brand	Model	Btm At
Other	1	3.00	7.063					2.37	5			21.00
Extended Neck tbg	hanger											
Tubing						1					į	21.00
Slotted SN				1		1						21.00

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Note: TA status "will be effective for a period up to 1 year from the date of NOI approval and can be renewed annually thereafter" per IM NM-2016-017.

- 1. A bridge plug (CIBP) or packer must be installed 50 to 100 feet above any open perforations or open hole. A CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 3. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 4. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 5. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 6. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.