Form 3160-5 (June 2015)

FORM APPROVED OMB NO. 1004-0137 expires: January 31, 2018 Lease Serial No. NMLC028793A

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT STATE
SUNDRY NOTICES AND REPORTS ON WELLS
A PLOS

Do not use this form for proposals to drill or to resemble and I A I LESIC abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or	Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM88525X	
Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. BURCH KEELY UNIT 403	
2. Name of Operator Contact: ROBYN RUSSELL COG OPERATING LLC E-Mail: rrussell@concho.com					9. API Well No. 30-015-35441-00-S1	
3a. Address 3b. Phone No. Ph: 432-68: MIDLAND, TX 79701			(include area code) 5-4385		10. Field and Pool or Exploratory Area BURCH KEELY-GLORIETA-UPR YES	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
Sec 19 T17S R30E NENW 250FNL 2130FWL					EDDY COUNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) T	O INDICA	ΓE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	☐ Deep	en	☐ Producti	on (Start/Resume)	■ Water Shut-Off
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	tion	■ Well Integrity
☐ Subsequent Report	Casing Repair	□ New	Construction	☐ Recomp	lete	Other Venting and/or Flari
☐ Final Abandonment Notice	☐ Change Plans		and Abandon	☐ Temporarily Abandon		ng
	Convert to Injection	Plug		☐ Water Disposal g date of any proposed work and appro		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. COG Operating LLC respectfully requests to flare at the Burch Keely Unit Satellite B Battery. Number of wells to flare: (34) Burch Keely Unit #29 (3001504190); Burch Keely Unit #49 (3001521265) Burch Keely Unit #50 (3001503078), Burch Keely Unit #55 (3001504201) Burch Keely Unit #58 (3001504192); Burch Keely Unit #55 (3001521657) Burch Keely Unit #62 (3001503081), Burch Keely Unit #239 (3001528018) Burch Keely Unit #242 (3001527652); Burch Keely Unit #239 (3001528018) Burch Keely Unit #242 (3001528333); Burch Keely Unit #244 (3001528089) Burch Keely Unit #262 (3001528033); Burch Keely Unit #269 (3001528018) Burch Keely Unit #321 (3001532098); Burch Keely Unit #322 (3001532108) DISTRICT II-ARTESIA O.C.D.						
14. I hereby certify that the foregoing is Con Name (Printed/Typed) ROBYN R	Electronic Submission #4: For COG OP nmitted to AFMSS for proces	ERATING L	.C, sent to the Ca SCILLA PEREZ or	arlsbad	(18PP2729SE)	
Signature (Electronic S	Submission)		Date 09/24/20	018		
	THIS SPACE FOI	R FEDERA			SE .	
/s/ Jonathon Shepard						-0CJateO 4 2018
_Approved By	Petrol	eum E	ingineer			
Conditions of approval, if any, are attached. Approval of this notice does not warrant concertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					ld Office	

Additional data for EC transaction #436606 that would not fit on the form

32. Additional remarks, continued

Burch Keely Unit #327 (3001532430); Burch Keely Unit #328 (3001532425)
Burch Keely Unit #334 (3001532702); Burch Keely Unit #335 (3001532701)
Burch Keely Unit #355 (3001532789); Burch Keely Unit #357 (3001532915)
Burch Keely Unit #358 (3001532916); Burch Keely Unit #359 (3001532969)
Burch Keely Unit #360 (3001532970); Burch Keely Unit #361 (3001532991)
Burch Keely Unit #379 (3001533816); Burch Keely Unit #384 (3001533813)
Burch Keely Unit #388 (3001533815); Burch Keely Unit #401 (3001535432)
Burch Keely Unit #402 (3001535440); Burch Keely Unit #403 (3001535441)

From 9/24/18 to 12/23/18 BBLS Oil/Day: 50 MCF/Day: 675

Reason: Unplanned Midstream curtailment. Plant shut down due to HLP or plant maintenance.

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval to Flare Gas

- 1. Approval not to exceed 180 days from date of submission.
- 2. All flaring under this request is considered to be "avoidably lost". Volumes for avoidably lost gas shall be reported on OGOR "B" reports as disposition code "33".

Exceptions:

- a. The first 24 hours of a temporary emergency flare is considered "unavoidably lost" and is therefore royalty free. Flared volumes that are considered unavoidably lost are not to be included in Sundry Notice (Form 3160-5). These Volumes are not royalty bearing and shall be reported on OGOR "B" as either disposition code "21" or "22".
- b. If the operator believes that the flared volumes were "unavoidably lost", the operator can submit a request via Sundry Notice (Form 3160-5) with justification for an exception in accordance with 43 CFR 3179.4, 3179.103 3179.105.