Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 018

Expir		anuar	
ase Serial N	o.		

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 5. Lease Serial No. NMNM56429

abandoned we	II. Use form 3160-3 (APD) for	such proposals.	6. If Indian, Allotte	e or Tribe Name
SUBMIT IN T	TRIPLICATE - Other instruction	ons on page 2	7. If Unit or CA/Ag	greement, Name and/or No.
Type of Well ☐ Gas Well ☐ Oth	ner	-	8. Well Name and N TRAVISTA FED	No.) 20
Name of Operator ROVER OPERATING LLC	Contact: KENN E-Mail: kpreston@roverp	NETH A PRESTON etro.com	API Well No. 30-015-2444	
3a. Address 17304 PRESTON ROAD SUI DALLAS, TX 75252		Phone No (include area of de)	10. Field and Pool LOCO HILLS	or Exploratory Area -QU-GB-SA
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11. County or Paris	sh, State
Sec 18 T18S R29E SENE 198	30FNL 330FEL		EDDY COUN	TY, NM
12. CHECK THE AI	PPROPRIATE BOX(ES) TO I	NDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA
TYPE OF SUBMISSION		TYPE OF	ACTION	
■ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off
	Alter Casing	☐ Hydraulic Fracturing	■ Reclamation	■ Well Integrity
☐ Subsequent Report	Casing Repair	■ New Construction	□ Recomplete	Other
☐ Final Abandonment Notice	Change Plans	□ Plug and Abandon	▼ Temporarily Abandon	
	□ Convert to Injection	Plug Back	■ Water Disposal	
Mr. Zota Stevens, Rover Petroleum respectfully Federal #20 on May 1, 2019. Proposed Procedure: MIRU	wishes to inform you of intent to This wellbore has potential utilit	temporarily abandon the y for future waterflood of Accepted for record	perations.	RECEIVED
ND WH, NU BOP POOH with rods, pump TOH with tubing RU WL. Set CIBP at 2400?, te	est CIBP & casing to 500#	Accepted for record		T 1 2 2018
Cap with 25 sxs cmt Notify BLM official and perform The approved unit				I-ARTESIA O.C.D.
14. I hereby certify that the foregoing is	Electronic Submission #43536	ATING LLC, sent to the C	arlsbad	
Name (Printed/Typed) BRADY W	•	Title ENGINE	•	
Signature (Electronic S	Submission)	Date 09/14/20	018	
	THIS SPACE FOR FE	DERAL OR STATE (OFFICE USE	
_Approved_By_ZQTA_STEVENS		TitlePETROLE	UM ENGINEER	Date 10/03/2018
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	intable title to those rights in the subjec		I	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s			willfully to make to any department	or agency of the United

Additional data for EC transaction #435364 that would not fit on the form

32. Additional remarks, continued

Clean loc, RDMO

ROVER PETROLEUM, LLC WELLBORE DIAGRAM - CURRENT

Lease/Well No.: TRAVIS D FEDERAL #20 ELEVATION, GL: 3506'

Location: 1,980' FNL & 330' FEL

UL: H, SEC: 18, T: 18-S, R:29-E FIELD: LOCO HILLS-QUEEN-GRAYBURG-SA


EDDY County, NM

API No. : **30-015-24441**

 Spudded:
 6/12/1983

 Drlg Stopped:
 6/18/1983

 Completed:
 7/15/1983



Tubing Count	Rod Count	Plugs
2-3/8" tubing	3/4" rods	N/A

FORMATIONS:

<u>TOPS</u>	DEPTH, ft
TOP OF SALT	340
BOT OF SALT	715
YATES	883
SEVEN RIVERS	1,215
QUEEN	1,881
GRAYBURG	2,250
METEX	2,450
PREMIER	2,584
SAN ANDRES	2,674

7-7/8" HOLE

TOC = SURF (CIRC)

Production Csg:
5-1/2" 15.5# J-55
Csg Set @ 2,801
- 41 /

Cmt'd w/ 950 sx
TOC = SURF (CIRC)

	• •	
		-
		 ≡
		=
		=
		 =
		 =
	2823' PBTD	

3360' TD

PERFORATIONS

DATE

DEPTHS	ZONE	SPF - # OF HOLES
2462' - 2466'	GB - Metex	1 spf - 4 holes
2481' -2485'	GB - Metex	1 spf - 4 holes
2496' - 2500'	GB - Metex	1 spf - 4 holes
2570' - 2574'	GB - Premier	1 spf - 4 holes
2593' - 2593'	GB - Premier	1 spf - 4 holes
2637' - 2641'	GB - Premier	1 spf - 4 holes
2646' - 2650'	GB - Premier	1 spf - 4 holes
2664' - 2668'	GB - Premier	1 spf - 4 holes
	TOTALS:	32 ' 32 holes

ROVER PETROLEUM, LLC WELLBORE DIAGRAM - PROPOSED

Lease/Well No.:

TRAVIS D FEDERAL #20

ELEVATION, GL: 3506'

Location:

1,980' FNL & 330' FEL

UL: H, SEC: 18, T: 18-S, R:29-E

FIELD: LOCO HILLS-QUEEN-GRAYBURG-SA

EDDY County, NM

API No.:

30-015-24441

Spudded:

6/12/1983

Drlg Stopped:

6/18/1983

Completed:

7/15/1983

12-1/4" HOLE

Surface Csg: 8-5/8" 24#

Csg Set @ 360' Cmt'd w/ 350 sx

TOC = SURF (CIRC)

7-7/8" HOLE

Production Csg: 5-1/2" 15.5# J-55 Csg Set @ 2,801' Cmt'd w/ 950 sx

TOC = SURF (CIRC)

2823' PBTD 3360' TD Tubing Count N/A Rod Count

N/A

Plugs 25 sxs cap @ 2400'

CIBP @ 2400'

DATE

FORMATIONS:

TOPS	DEPTH, ft
TOP OF SALT	340
BOT OF SALT	715
YATES	883
SEVEN RIVERS	1,215
QUEEN	1,881
GRAYBURG	2,250
METEX	2,450
PREMIER	2,584
SAN ANDRES	2,674

PERFORATIONS

DEPTHS	ZONE	SPF - # OF HOLES
2462' - 2466'	GB - Metex	1 spf - 4 holes
2481' -2485'	GB - Metex	1 spf - 4 holes
2496' - 2500'	GB - Metex	1 spf - 4 holes
2570' - 2574'	GB - Premier	1 spf - 4 holes
2593' - 2593'	GB - Premier	1 spf - 4 holes
2637' - 2641'	GB - Premier	1 spf - 4 holes
2646' - 2650'	GB - Premier	1 spf - 4 holes
2664' - 2668'	GB - Premier	1 spf - 4 holes
	TOTALS:	32 ' 32 holes

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

. . . .

- a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing.
- p. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
- c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612
- 3. Provides justification why the well should be temporarily abandoned rather than beginnently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA:status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Golden Spur Federal 001H Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 6 months or until 08/01/2018 after successful MIT and subsequent report is submitted. This well has been shut-in since November 2016.