



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

Juanna Prukop

Cabinet Secretary

**Mark E. Fossire, P.E.**

Director

Oil Conservation Division

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

RECEIVED

APR 26 2006

COMPTON

04-Apr-06

**PURE RESOURCES, LP**  
500 W ILLINOIS AVE  
MIDLAND TX 79701

## LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### INSPECTION DETAIL SECTION

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	30-015-23675-00-00 Corrosive Action Due By:	Inspection No.
03/29/2006	Routine/Periodic	Chris Beadle	Yes	No	4/15/2006	ICLB0608838042

**Violations**

Tank Battery Equipment (Rules 114, 115)

Comments on Inspection: Net on water tank is down, inside tank. Liquids in tank have heavy layer of oil. Net must be replaced or repaired immediately.

Contact NMOCD District 2 Office when net has been replaced or repaired.

NET REPAIRED AND STRETCHED OVER TOP OF TANK,  
TANK EMPTIED OF FLUID,  
COMPLETE 4/20/06.

Accepted for record - NMOCD

LARRY D RIDEAUR  
OPERATIONS REPRESENTATIVE