Submit One Copy To Appropriate District ASCENED State of	New Mexico	Form C-103
District I Energy, Minerals	and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 NOV 68 2018 OIL CONSERVATION DIVISION		WELL API NO. 30-015-24898
		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd Aziec NM 87419	h St. Francis Dr.	STATE STATE FEE
District III 1000 Rio Brazos Rd., Aztec, NM 87 DISTRICT II-ARTESIA 9. Sout District IV Santa F	e, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		New Mexico Z State
1. Type of Well: Oil Well Gas Well Other		8. Well Number 002
2. Name of Operator COG Operating LLC		9. OGRID Number 229137
3. Address of Operator		10. Pool name or Wildcat
2208 W. Main Street, Artesia NM 88210		Millman; Yates-SR QN-GB-SA, East
4. Well Location		
Unit Letter <u>B</u> : 660 feet from the <u>No</u>	orth line and 1980	feet from the <u>East</u> line
Section 12 Township 19S	Range 28E	NMPM County <u>Eddy</u>
11. Elevation (Show w	hether DR, RKB, RT, GR, etc.,)
12. Check Appropriate Box to Indicate Nature of I	3345' Notice, Report or Other D	Pata
	•	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		
PULL OR ALTER CASING MULTIPLE COMPL	☐ CASING/CEMEN	
	_ _	
OTHER: Description Descri		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
ODED ATOD NAME I FACE NAME WELL NUMBED ADJUMDED OUADTED/OUADTED LOCATION OD		
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u>		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease	· all electrical service noles an	d lines have been removed from lease and well
location, except for utility's distribution infrastructure.	an electrical service poles and	a lines have been tenno visit and wen
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE 1	TITLE: Regulatory Tech	DATE <u>11/6/2018</u>
TYPE OR PRINT NAME _Delilah Flores	_E-MAIL: dflores2@concho.	com PHONE: <u>575-748-6946</u>
For State Use Only		
APPROVED BY:	///	DATE //-/6-/8
AFFRUYCU DI CACCOLO	TITIES OF L	DATE //-/ & -/ X