	NM CL CONSERVATION						
	UNITED STATES PARTMENT OF THE II JREAU OF LAND MANA	NOV 2 0 2018		FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018			
SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED				VED	5. Lease Serial No. NMNM114979		
Do not use this form for proposals to drill or to re-enter and the bar abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM137096X		
1. Type of Well Image: State St					8. Well Name and No. MESA VERDE BS UNIT 20		
2. Name of Operator OXY USA INCORPORATED E-Mail: SARAH_CHAPMAN@OXY.COM					9. API Well No. 30-015-44547-00-X1		
3a. Address 5 GREENWAY PLAZA SUITE HOUSTON, TX 77046-0521	(include area code) 0-4997	bde) 10. Field and Pool or Exploratory Area MESA VERDE-BONE SPRING					
4. Location of Well <i>(Footage, Sec., T)</i>	11. County or Parish, State			State			
Sec 13 T24S R31E SWSW 17 32.210587 N Lat, 103.737221		EDDY COUNTY, NM					
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE	, REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	Acidize Alter Casing	Deep	pen raulic Fracturing	Produc	tion (Start/Resume)	 □ Water Shut-Off □ Well Integrity ☑ Other 	
Subsequent Report	Casing Repair		Construction		olete		
Final Abandonment Notice	Change Plans		g and Abandon 🛛 🗖 Tem		Drilling Operations		
	Convert to Injection Plug Back				Water Disposal e of any proposed work and approximate duration thereof.		
15. Describe Proposed of Completed Op If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 10/26/18 MIRU, test BOP @ 2 good test. RIH & drill new forr Drill 6-3/4" hole to 15544'M/10 15544'-10521' and 5-1/2" 20# w/ 679sxs (168bbl) class C w/	ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re bandonment Notices must be fi inal inspection. 250# low 5000# high, goo nation to 9960', perform f 0590'V. RIH & set tapered P110 DQX csg @ 10519	, give subsurface the Bond No. or ssults in a multipl led only after all od test. Test 7 FIT test to EM d string w/ 4-1 9'- 0'. Pump 90	locations and measu n file with BLM/BIA e completion or recor- requirements, includ -5/8" csg to 4100 W=11ppg 1250p /2" 13.5# P110 E bbl mud push e:	red and true v Required su impletion in a ing reclamation w for 30 mi si, good tes QX csg @ xpress spa	ertical depths of all pertir ibsequent reports must be new interval, a Form 316 on, have been completed a nutes, st.	filed within 30 days 0-4 must be filed once	
TOC=9490' (450' inside shoe). 11/2/18 RD and rig rele	ase to Cedar	Canyon 28 Fed	41H.	Accepted Fo NMOC	r Record	
14. I hereby certify that the foregoing i	s the and correct		<u> </u>				
	Electronic Submission a	A INCORPORA	TED, sent to the	Carlsbad			
Committed to AFMSS for processing by PRISCILLA PEREZ on 11/13/2018 (19PP0369SE)							
Name (Printed/Typed) DAVID S							
Signature (Electronic Submission) Date				ate 11/13/2018			
	THIS SPACE F	OR FEDER	AL OR STATE	OFFICE (JSE		
APProved By ACCEPTED			ZOTA STEVENS TitlePETROLEUM ENGINEER Date 11/13/2018				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad				
Title 18 U.S.C. Section 1001 and Title 4 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it statements or representations a	a crime for any p as to any matter v	erson knowingly and vithin its jurisdiction	l willfully to a	make to any department o	r agency of the United	
(Instructions on page 2) ** BLM REV	/ISED ** BLM REVISE	D ** BLM R	EVISED ** BLI	M REVISE	D ** BLM REVISE	D **	