
Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMNM104730 6. If Indian, Allottee or Tribe Name	
1. Type of Well Gas Well Other: INJECTION				8. Well Name and No. SAND DUNES SWD 1	
2. Name of Operator Contact: MELANIE WILSON MESQUITE SWD INC E-Mail: mjp1692@gmail.com				I No. -44612	
3a. Address PO BOX 1479 CARLSBAD, NM 88221	Phone No. (include area code): 575-914-1461		10. Field and Pool or Exploratory Area SWD; DEVONIAN		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	11. County	or Parish, State		
Sec 5 T24S R31E Mer NMP SESW 260FSL 2053FWL				COUNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NATURE O	F NOTICE, REPORT,	OR OTHER DATA	
TYPE OF SUBMISSION	-	ТҮРЕ ОР	ACTION		
☐ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Re	esume)	
_	☐ Alter Casing	☐ Hydraulic Fracturing	■ Reclamation	■ Well Integrity	
Subsequent Report	□ Casing Repair	■ New Construction	□ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon		
	□ Convert to Injection	□ Plug Back	■ Water Disposal		
If the proposal is to deepen directional Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit 10/11/2018 - Ran 5-1/2" 20# T packer @ 16413'. 10/12/2018 to 10/14/2018 - Cit 10/24/2018 - Pressure test to see the Bond attachment of the Bond attachme	rk will be performed or provide the B operations. If the operation results in andonment Notices must be filed onlinal inspection. 195 tbg 10990-16413' and 7" 2 orc 500 bbls packer fluid. Test of	ond No. on file with BLM/BIA n a multiple completion or reco y after all requirements, include 16# P110 tbg from surface csg to 500# for 30 mins. F	Required subsequent repoint properties of the subsequent repoint and the subsequent repoint re	rts must be filed within 30 days a Form 3160-4 must be filed once	
first injection.		•		1 (EAC) 4 CD	
MIT Chart attached.	Accept	ed for record - NMOCI	8	OCT 2 5 2018	
			DIS	STRICT II-ARTESIA O.C.D.	
14. I hereby certify that the foregoing is	Electronic Submission #44112	4 verified by the BLM Well SWD INC, sent to the Car	Information System Isbad		
Name (Printed/Typed) MELANIE	Title REGUL	ATORY ANALYST			
Signature (Electronic S	submission)	Date 10/25/20)18		
	THIS SPACE FOR F	EDERAL OR STATE (OFFICE USE		
Approved By		Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		arrant or		, 240	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime	for any person knowingly and	willfully to make to any dep	artment or agency of the United	



State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen **Cabinet Secretary**

Matthias Sayer

Heather Riley, Division Director Oil Conservation Division



Deputy Cabinet Secretary	COMBERVATION UND
	Date: 10 - 24-18
	API# 30-015-44612
A Mechanical Integrity Test (M.I.T.) was performed on,	Well SAnd Dunes SWD 001
M.I.T. is successful, the original chart has been reta scan of the chart with an attached Original C-103 Form District NMOCD field office. A scanned image will appea www.emnrd.state.nm.us/ocd/OCDOnllne.htm 7 to 10 day	nined by the Operator on site. Send a legible indicating reason for the test, via post mail to ar online via NMOCD website,
M.I.T. is unsuccessful, the original chart is returne Operator is to schedule for a re-test within a 90-day per in non-compliance, all dates and requirements of the or No expectation of extension should be construed be	riod. If this is a test of a repaired well currently riginal are still in effect.
M.I.T. for Temporary Abandonment, shall include the location of the CIBP and any other tubular goods in t status timeline.	
M.I.T. is successful, after the secondary request of Operator has within a 30-day period from the M.I.T. to so the Chart, including a detailed description of the repair(s compliance be closed.	ubmit a current C-103 along with a legible scan of
M.I.T.is successful, Initial of an injection well, you 30 days. A C-103 form must include a detailed description the position of the packer, tubing Information, the date Injection volume.	ion of the work performed on this well Including
Please contact Rusty Klein at 575-748-1283 x109 for verequirements are in place prior to injection process.	erification to ensure documentation
If I can be of additional assistance, please feel free to	o contact me at (575) 748-1283 ext. 114.
Thank You,	
Gilbert Cordero, Staff Manager EMNRD-O.C.D.	RECEIVED
District II – Artesia, NM	OCT 2 5 20

DISTRICT II-ARTESIA O.C.D.