DEC 0 7 2018

Submit One Copy To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals an Warlfall Resturates O	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	30-015-33004
811 S. First St., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE S FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Todd 2 State
	ATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number
PROPOSALS.)	Cara Wall Modern	15
1. Type of Well: Oil Well	Gas well 🖂 Other	9. OGRID Number
2. Name of Operator Chevron USA Inc.		4323
3. Address of Operator		10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX	70706	Ingle Wells, Delaware
		mgie wens, Delaware
4. Well Location: Wellhead location 32.248233,-103.746459		
Unit Letter_G:_1,980_feet from the North line and 1980 feet from the East line		
Section 2 Township 24-S Range 31E NMPM County Eddy		
	11. Elevation (Show whether DR, RKB, RT, GR, et	(c.)
	3,501'	
12. Check Appropriate Box to	Indicate Nature of Notice, Report or Other	Data
NOTICE OF IN	FENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	ORK \square ALTERING CASING \square
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE D	RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	NT JOB
OTHER:		ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
		
to be removed.)	is have been addressed as per OCD rules.	
	en abandoned in accordance with 19.15.35.10 NMA	C. All fluids have been removed from non-
retrieved flow lines and pipelines.	an abandoned in accordance with 19.15.55.10 INVIA	C. All fidids have been removed from fion-
	remaining well on lease: all electrical service poles	and lines have been removed from lease and well
location, except for utility's distributi		and fines have been removed from lease and wen
location, except for utility's distributi	on mirasu ucture.	
When all work has been completed r	eturn this form to the appropriate District office to s	chedule an inspection
when an work has been completed, i	cturn this form to the appropriate District office to s	enedule all hispection.
	n e	
SIGNATURE Atherine F	PapageorgeTITLEDecommissionir	g Project ManagerDATE12.3.18
	ne Papageorge_E-MAIL: _Katherine.Papageorge@	chevron.com PHONE:832-854-5291
For State Use Only		
200	CLM	1 11 10
APPROVED BY:	TITLE 27AH	DATE /2 -//-/8