

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No.
OILC028784A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit or CA/Agreement, Name and/or No.
NMNM88525X

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

8. Well Name and No.
BURCH KEELY UNIT 84

2. Name of Operator
COG OPERATING LLC

Contact: SANDY BALLARD
E-Mail: sballard@concho.com

9. API Well No.
30-015-03070-00-S1

3a. Address
600 W ILLINOIS AVENUE
MIDLAND, TX 79701

3b. Phone No. (include area code)
Ph: 432-686-4373

10. Field and Pool or Exploratory Area
GRAYBURG

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 24 T17S R29E NWSW 1980FSL 660FWL

11. County or Parish, State
EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Venting and/or Flaring
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Burch Keely Unit 84
Burch Keely Unit 23A Battery
(Permit approval: Electronic Submission # 404927)
Actual gas flared for this battery for 5/31/2018 TO 8/29/2018 is as follows:

May
Total for Battery = 0 MCF
June
Total for Battery = 1316 MCF
July
Total for Battery = 0 mcf
Aug

NM OIL CONSERVATION
ARTESIA DISTRICT

12/14/18
Accepted for record
NMOCDC
RECEIVED
DEC 12 2018

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #445372 verified by the BLM Well Information System

For COG OPERATING LLC, sent to the Carlsbad

Committed to AFMSS for processing by PRISCILLA PEREZ on 11/30/2018 (19PP0473SE)

Name (Printed/Typed) SANDY BALLARD

Title SENIOR ADMINISTRATIVE ASSISTANT

Signature (Electronic Submission)

Date 11/28/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

NOV 30 2018

/s/ Jonathon Shepard

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #445372 that would not fit on the form

32. Additional remarks, continued

Total for Battery = 0 mcf

NUMBER OF WELLS TO FLARE: (30)

BURCH-KEELY UNIT 84 30-015-03070

BURCH-KEELY UNIT 111 30-015-21294

BURCH-KEELY UNIT 112 30-015-03075

BURCH-KEELY UNIT 116 30-015-03066

BURCH-KEELY UNIT 132 30-015-03084

BURCH-KEELY UNIT 134 30-015-03087

BURCH-KEELY UNIT 227 30-015-28687

BURCH-KEELY UNIT 230 30-015-27991

BURCH-KEELY UNIT 254 30-015-28585

BURCH-KEELY UNIT 266 30-015-28886

BURCH-KEELY UNIT 278 30-015-29809

BURCH-KEELY UNIT 281 30-015-29511

BURCH-KEELY UNIT 305 30-015-30491

BURCH-KEELY UNIT 312 30-015-31434

BURCH-KEELY UNIT 314 30-015-31526

BURCH-KEELY UNIT 338 30-015-32756

BURCH-KEELY UNIT 339 30-015-32700

BURCH-KEELY UNIT 378 30-015-33814

BURCH-KEELY UNIT 406H 30-015-35564

BURCH-KEELY UNIT 603 30-015-40275

BURCH-KEELY UNIT 608 30-015-38571

BURCH-KEELY UNIT 611 30-015-38646

BURCH-KEELY UNIT 632 30-015-40327

BURCH-KEELY UNIT 850 30-015-40375

BURCH-KEELY UNIT 859 30-015-40383

BURCH-KEELY UNIT 860 30-015-40384

BURCH-KEELY UNIT 900 30-015-40885

BURCH-KEELY UNIT 901 30-015-40886

BURCH-KEELY UNIT 952H 30-015-42760

BURCH-KEELY UNIT 958H 30-015-42242

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT MAINTENANCE AND HLP