' Form 3160-5 (June 2015)

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT APPLIES DAD

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY his form for proposals to drill or to re-edition 1

Lease Serial No.

abandoned wel	s form for proposals to drill on. 1. Use form 3160-3 (APD) for	such proposals.	Artesia	ndian, Allottee or Tri	be Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NMNM88525X		
1. Type of Well				8. Well Name and No. BURCH KEELY UNIT 23		
2. Name of Operator Contact: SANDY BALLARD				9. API Well No.		
COG OPERATING LLC E-Mail: sballard@concho.com				30-015-20417-00-S1		
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	Phone No. (include area cod 432-686-4373		10. Field and Pool or Exploratory Area GRAYBURG			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. C	11. County or Parish, State		
Sec 18 T17S R30E NESW 1980FSL 1894FWL				EDDY COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Sta	art/Resume)	Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation		Well Integrity	
Subsequent Report	□ Casing Repair	☐ New Construction	Recomplete		Other enting and/or Flari	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily A	oandon n	-	
13. Describe Proposed or Completed Ope	☐ Convert to Injection	☐ Plug Back	☐ Water Disposa			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Burch Keely Unit 23 Burch Keely Unit 18B Battery (Permit approval: Electronic Submission #404914) Actual gas flared for this battery for 3/1/2018 TO 5/30/2018 is as follows: March Total for Battery = 0 MCF April Total for Battery = 0 MCF May Total for Battery = 0 mcf NM OIL CONSERVATION ARTESIA DISTRICT DEC 1 2 2018 NIMOCD RECEIVED						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #445363 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 11/30/2018 (19PP0469SE) Name (Printed/Typed) SANDY BALLARD Title SENIOR ADMINISTATIVE ASSISTANT						
, , , , , , , , , , , , , , , , , , ,				,		
Signature (Electronic S	Date 11/28/					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By		Title	TUR RELUK	ו	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		urrant or NOV	3 0 2018 /8	s/Jonathon	Shepard	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime futatements or representations as to any	for any person knowingly ar matter within its julisdiction	id willfully to make to as	ny department or ager	cy of the United	
		S. WOULDELL	CIESTELL (MACHE)	ı	_	

Additional data for EC transaction #445363 that would not fit on the form

32. Additional remarks, continued

```
NUMBER OF WELLS TO FLARE: (25)
BURCH-KEELY UNIT 23 30-015-20417 **
BURCH-KEELY UNIT 25 30-015-20418 **
BURCH-KEELY UNIT 27 30-015-04188 **
BURCH-KEELY UNIT 28 30-015-04188 **
BURCH-KEELY UNIT 28 30-015-04188 **
BURCH-KEELY UNIT 257 30-015-29035 **
BURCH-KEELY UNIT 275 30-015-29774 **
BURCH-KEELY UNIT 297 30-015-30731 **
BURCH-KEELY UNIT 303 30-015-30789
BURCH-KEELY UNIT 329 30-015-30789
BURCH-KEELY UNIT 347 30-015-32426
BURCH-KEELY UNIT 351 30-015-32426
BURCH-KEELY UNIT 353 30-015-32787
BURCH-KEELY UNIT 353 30-015-32787
BURCH-KEELY UNIT 382 30-015-33811
BURCH-KEELY UNIT 396 30-015-33810
BURCH-KEELY UNIT 404 30-015-35434
BURCH-KEELY UNIT 570 30-015-40267
BURCH-KEELY UNIT 573 30-015-40267
BURCH-KEELY UNIT 573 30-015-40268
BURCH-KEELY UNIT 578 30-015-40268
BURCH-KEELY UNIT 578 30-015-39539
BURCH-KEELY UNIT 585 30-015-39540
BURCH-KEELY UNIT 586 30-015-39908
BURCH-KEELY UNIT 586 30-015-39908
BURCH-KEELY UNIT 941H 30-015-40971
Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT MAINTENANCE AND HLP
```