

District II - Artesia811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

RECEIVED

DEC 17 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

DISTRICT II-ARTESIA O.C.D.

BRADENHEAD TEST REPORT

Operator Name Pogo oil & gas		API Number 30-015-10101	
Property Name North Benson Queen Unit		Well No. 9	

7. Surface Location

UL - Lot F	Section 28	Township 18S	Range 30E	Feet from 2310'	N/S Line N	Feet From 1980'	E/W Line W	County eddy
----------------------	----------------------	------------------------	---------------------	---------------------------	----------------------	---------------------------	----------------------	-----------------------

Well Status

TA'D Well YES (NO)	SHUT-IN YES (NO)	INJECTOR (INJ) SWD	PRODUCER OIL GAS	DATE 11/15/18
------------------------------	----------------------------	------------------------------	---------------------	-------------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure				650	
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	(Y/N)	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	(Y/N)	WTR _____
Surges	Y/N	Y/N	Y/N	(Y/N)	GAS _____
Down to nothing	(Y/N)	Y/N	Y/N	(Y/N)	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	(Y/N)	fluid injected for
Water	Y/N	Y/N	Y/N	(Y/N)	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dan Smolik		OIL CONSERVATION DIVISION	
Printed name: Dan Smolik		Entered RBDMS	
Title: Compliance officer		Re-test	
E-mail Address: danny.smolik@state.nm.us			
Date:	Phone: 622-0836		
	Witness:		