

District II - Artesia811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575)-748-9720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name <i>Trinity environmental 1 SWD LLC</i>	API Number <i>30-015-22893</i>
Property Name <i>Red lake state SWD</i>	Well No. <i># 001</i>

7. Surface Location

UL - Lot <i>6</i>	Section <i>22</i>	Township <i>17S</i>	Range <i>28 E</i>	Feet from <i>1900</i>	N/S Line	Feet From <i>1900</i>	E/W Line	County <i>Eddy</i>
----------------------	----------------------	------------------------	----------------------	--------------------------	----------	--------------------------	----------	-----------------------

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES NO	YES NO	INJ SWD	OIL GAS	<i>Eddy 11-26-18</i>

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

No Pressure

Signature: <i>Dan Smolik</i>	OIL CONSERVATION DIVISION
Printed name: Dan Smolik	Entered RBDMS
Title: Compliance officer	Re-test
E-mail Address: danny.smolik@state.nm.us	
Date: <i>11-26-18</i>	Phone: <i>624-0836</i>
Witness: <i>[Signature]</i>	