Submit One Copy To Appropria Office	ne Copy To Appropriate District State of New Mexico				Form C-103
District I 1625 N. French Dr., Hobbs, NM				Revised November 3, 2011 WELL API NO.	
District II 811 S. First St., Artesia, NM 882				30-015-22228	
District III	ELIII 1220 South St. Francis Dr.			5. Indicate Type of Lease STATE X FEE	
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM			 State Oil & Gas Lease No. V-689 		
87505 SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				SST	
PROPOSALS.) NM OIL CONSERVATION 1. Type of Well: XOII Well 2. Name of Operator MATADOR PRODUCTION COMPANY DEC 2.0 CORRID Number 9.0 CORD 228.037					
		IPANY D	EC 20 2018	9. OGRID Number 228937	
	5400 LBJ FREEWAY, SU DALLAS TX 75240	UITE 1500		 Pool name or Wild PALMILLO; BONE 	
4. Well Location Unit Letter <u>G</u> : 1980 feet from the NORTH line and 1980 feet from the EAST line					
Section 06 Township 195 Range 29E NMPM County EDDY					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
OTHER:					
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.					
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR					
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR					
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment <u>TANK BATTERY SHARED WITH ACTIVE WELLS</u>					
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.					
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed					
from lease and well location. For the the set of the se					
to be removed.) Buried Former Line wat removed					
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-					
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well					
location, except for utility's	distribution infrastructure.				r nom lease and wen
When all work has been completed, return this form to the appropriate District office to schedule an inspection.					
SIGNATURE	Ni	TITLE	ENGINE	ERDATE	12/20/18
TYPE OR PRINT NAME	CHRIS VILLARREAL	E-MAIL:	CVILLARREAL@MATADO	RRESOURCES.COM PHON	E: (972)371-5471
For State Use Only	nchich		EDE BAAS		GC
APPROVED BY:	DENIEU		LENI	DAT	Е <u> /2 - 27-1</u> 8

ン

ſ