

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

Lease Serial No.
NMLC029419A

SUBMIT IN TRIPLICATE - Other instructions on page 2		6. If Indian, Allottee or Tribe Name
1. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other		7. If Unit or CA/Agreement, Name and/or No. 892000276B
2. Name of Operator CHEVRON USA INCORPORATED Contact: SANDY BALLARD E-Mail: sballard@concho.com		8. Well Name and No. SKELLY UNIT 940
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706	3b. Phone No. (include area code) Ph: 432-686-4373	9. API Well No. 30-015-32599-00-S1
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 22 T17S R31E NWNW 990FNL 330FWL		10. Field and Pool or Exploratory Area FREN PADDOCK
		11. County or Parish, State EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other Venting and/or Flaring
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Skelly Unit 940
Skelly Unit 940 Battery
Permit approval: Electronic Submission # 411886
Actual gas flared for this battery for 4/20/2018 TO 7/19/2018 is as follows:
April
Total for Battery = 14462 MCF
May
Total for Battery = 1626 MCF
June
Total for Battery = 14726 MCF
Number of wells to flare: (63)
SKELLY UNIT 635 30-015-37657-00-S01

RECEIVED

Accepted for record
NMOCD
11/14/19 AB

JAN 10 2019

DISTRICT II-ARTESIA O.C.D.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #446334 verified by the BLM Well Information System For CHEVRON USA INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 12/10/2018 (19PP0561SE)	
Name (Printed/Typed) SANDY BALLARD	Title SENIOR ADMINISTRATIVE ASSISTANT
Signature (Electronic Submission)	Date 12/04/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By _____	Title _____	Date _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office _____	/s/ Jonathon Shepard

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #446334 that would not fit on the form

32. Additional remarks, continued

SKELLY UNIT 645 30-015-40727-00- ✓
SKELLY UNIT 646 30-015-38362-00- ✓
SKELLY UNIT 655 30-015-39145-00- ✓
SKELLY UNIT 660 30-015-37245-00- ✓
SKELLY UNIT 661 30-015-40092-00- ✓
SKELLY UNIT 665 30-015-39347-00- ✓
SKELLY UNIT 669 30-015-38348-00- ✓
SKELLY UNIT 673 30-015-40093-00- ✓
SKELLY UNIT 678 30-015-37474-00- ✓
SKELLY UNIT 679 30-015-37820-00- ✓
SKELLY UNIT 682 30-015-37477-00- ✓
SKELLY UNIT 688 30-015-40102-00- ✓
SKELLY UNIT 698 30-015-40103-00- ✓
SKELLY UNIT 710 30-015-37969-00- ✓
SKELLY UNIT 715 30-015-38346-00- ✓
SKELLY UNIT 725 30-015-38378-00- ✓
SKELLY UNIT 737 30-015-40095-00- ✓
SKELLY UNIT 747 30-015-40096-00- ✓
SKELLY UNIT 750 30-015-38284-00- ✓
SKELLY UNIT 753 30-015-38252-00- ✓
SKELLY UNIT 757 30-015-38363-00- ✓
SKELLY UNIT 759 30-015-38672-00- ✓
SKELLY UNIT 767 30-015-37476-00- ✓
SKELLY UNIT 769 30-015-38361-00- ✓
SKELLY UNIT 771 30-015-38104-00- ✓
SKELLY UNIT 782 30-015-38015-00- ✓
SKELLY UNIT 783 30-015-37885-00- ✓
SKELLY UNIT 785 30-015-40097-00- ✓
SKELLY UNIT 802 30-015-38347-00- ✓
SKELLY UNIT 810 30-015-38450-00- ✓
SKELLY UNIT 820 30-015-37886-00- ✓
SKELLY UNIT 827 30-015-38350-00- ✓
SKELLY UNIT 828 30-015-38443-00- ✓
SKELLY UNIT 829 30-015-37983-00- ✓
SKELLY UNIT 832 30-015-37984-00- ✓
SKELLY UNIT 833 30-015-38448-00- ✓
SKELLY UNIT 843 30-015-37985-00- ✓
SKELLY UNIT 847 30-015-40729-00- ✓
SKELLY UNIT 849 30-015-37517-00- ✓
SKELLY UNIT 901 30-015-29326-00-0 ✓
SKELLY UNIT 935 30-015-31977-00- ✓
SKELLY UNIT 939 30-015-32598-00- ✓
SKELLY UNIT 940 30-015-32599-00- ✓
SKELLY UNIT 943 30-015-32962-00- ✓
SKELLY UNIT 944 30-015-32963-00- ✓
SKELLY UNIT 945 30-015-32964-00- ✓
SKELLY UNIT 946 30-015-32965-00- ✓
SKELLY UNIT 947 30-015-32966-00- ✓
SKELLY UNIT 948 30-015-32967-00- ✓
SKELLY UNIT 949 30-015-32968-00- ✓
SKELLY UNIT 958 30-015-34318-00- ✓
SKELLY UNIT 959 30-015-34327-00- ✓
SKELLY UNIT 961 30-015-34324-00-S1 ✓
SKELLY UNIT 962 30-015-34325-00-S1 ✓
SKELLY UNIT 963 30-015-34646-00- ✓
SKELLY UNIT 964 30-015-34686-00- ✓
SKELLY UNIT 976 30-015-38251-00- ✓
SKELLY UNIT 978 30-015-36062-00-S01 ✓
SKELLY UNIT 979 30-015-38342-00-0 ✓
SKELLY UNIT 980 30-015-36063-00-S01 ✓
SKELLY UNIT 987 30-015-36497-00- ✓
SKELLY UNIT 995 30-015-36473-00-S01 ✓

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT MAINTENANCE AND HLP