Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018

5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS A FIELD OF MALCO58181

Do not use this form for proposals to drift-of the field of the abandoned well. Use form 3160-3 (APD) for such propess 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Well Name and No **BEECH 25 FEDERAL 9H** ☑ Oil Well ☐ Gas Well ☐ Other 2. Name of Operator
COG OPERATING LLC Contact: SANDY BALLARD API Well No. E-Mail: sballard@concho.com 30-015-40208-00-S1 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 600 W ILLINOIS AVENUE Ph: 432-686-4373 **RED LAKE** MIDLAND, TX 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec 25 T17S R27E SWSW 990FSL 180FWL EDDY COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Production (Start/Resume) ■ Water Shut-Off ☐ Acidize □ Deepen ■ Notice of Intent ■ Well Integrity □ Alter Casing ☐ Hydraulic Fracturing ☐ Reclamation Subsequent Report Other Casing Repair ■ New Construction ☐ Recomplete Venting and/or Flari ☐ Final Abandonment Notice □ Change Plans □ Plug and Abandon ☐ Temporarily Abandon ☐ Plug Back ☐ Water Disposal □ Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Beech 25 Federal 9H Beech 24 Federal #9H Battery Permit approval: Electronic Submission # 419066 Actual gas flared for this battery for 5/8/2018 TO 8/06/2018 is as follows: May RECEIVED Total for Battery = 2094 MCF June Total for Battery = 92 MCF Accepted for record JAN 1 0 2019 July Total for Battery = 0 MCF DISTRICT II-ARTESIA O.C.D. Number of wells to flare: (4) 14. I hereby certify that the foregoing is true and correct. Electronic Submission #446533 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 12/10/2018 (19PP0568SE) Title SENIOR ADMINISTATIVE ASSISTANT Name (Printed/Typed) SANDY BALLARD Signature (Electronic Submission) 12/05/2018 THIS SPACE FOR FEDERAL OR STATE OFFICE USE. Date Approved By Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or DEC 1 2 2018 /s/ Jonathon Shepard certify that the applicant holds legal or equitable title to those rights in the subject lease

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction; OF 1 AN'. 1. (1.1.4)

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United

Office

which would entitle the applicant to conduct operations thereon.

Additional data for EC transaction #446533 that would not fit on the form

32. Additional remarks, continued

BEECH 25 FEDERAL # 9H 30-015-40208 /
BEECH 25 FEDERAL #10H 30-015-42363 /
BEECH 25 FEDERAL #11H 30-015-43176 /
BEECH 25 FEDERAL #12H 30-015-43181 /
Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT DUE TO PLAINT MAINTENANCE OR HLP.
PLANT HAVING MECHANICAL ISSUES AND REQUESTED SHORT NOTICE TO CURTAIL 5M.