Office	of New Mexico	Form C-103
District I RECEIVED Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II OH. CONSERNATION DIVISION		30-015-23635
District II 811 S. First St., Artesia, NM 88210 JAN 2 2 2019 L CONSERVATION DIVISION District III 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Fo. NIM 97505		STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Sama Fe, NM 87505 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Jackson Estate BY
PROPOSALS.)		8. Well Number
Type of Well:		9. OGRID Number
EOG Y Resources, Inc.		9. OGRID Number 025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210		Eagle Creek; San Andres
4. Well Location		
Unit Letter K: 2310 feet from the South line and 2310 feet from the West line		
Section 22 Township	17S Range 25E	NMPM Eddy County
11. Elevation (Show	whether DR, RKB, RT, GR, etc.) 3542' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDO		
TEMPORARILY ABANDON	☐ COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPL	☐ CASING/CEMENT	JOB
OTHER:	☐ ⊠ Location is re	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
TOTAL		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. Power Lines Poles Not remove Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
Anchors, dead men, the downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. Burned Power Line Not Removed. (Poured onsite concrete bases do not have		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.) Casing thist be Cat 3' BGL (See CoA's) All other environmental concerns have been addressed as per OCD rules. This Land meta)		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. No, active pipeline(s) within EOG Y Resources gas system.		
☐ If this is a one-well lease or last remaining well on least		l lines have been removed from lease and well
location, except for utility's distribution infrastructure. CVE has been notified. When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
of A A A A A A A A A A A A A A A A A A A		
SIGNATURE_	TITLE: Environmental Sur	pervisor DATE 1/21/2019
TYPE OR PRINT NAME: Robert Asher	E-MAIL: <u>Robert_Asher@e</u>	ogresources.com PHONE: 575-748-4217
For State Use Only	ED ET REERT	
APPROVED BY:	TITLE DENIE	DATE 1/23/19
Conditions of Approval (if any):		