Submit One Copy To Appropriate District RECEIVED State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240  JAN 2 5-2010	WELL API NO. 30-015-26401
811 S. First St., Artesia, NM 88210 OLE CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NASTRICT II-ARTESIA O.O.D.nta Fe, NM 87505	STATE X FEE
District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	SAND DUNE STATE
PROPOSALS.)	0. 11. 11. 11.
1. Type of Well: X Oil Well Gas Well Other	8. Well Number #5
Name of Operator     EOG RESOURCES, INC	9. OGRID Number
3. Address of Operator	7377 10. Pool name or Wildcat
PO BOX 2267 MIDLAND, TEXAS 79702	10. 1 001 manie of Wildeat
4. Well Location	
Unit Letter N: 990 feet from the SOUTH line and 1980 feet from the WEST line	
Section 11 Township 19S Range 29E NMPM County Eddle	
11. Elevation (Show whether DR, RKB, RT, GR, e	tc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WO	
TEMPORARILY ABANDON	PRILLING OPNS. P AND A
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEME	ENT JOB
OTHER:   Location is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. What I also be the cleared of an junk, trash, now lines and	
other production equipment. What ker Needs to be Rollace I Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to s	schedule an inspection.
V 100 0 1 1 1 1	
SIGNATURE YOU WILL TITLE: REGULATORY S	SPECIALIST DATE 01/24/2019
TYPE OR PRINT NAME: KAY MADDOX E-MAIL: <u>kay_maddox@eogresources.com</u> PHONE: _432-686-3658	
For State Use Only	_
APPROVED BY:IIILE	DATE 1/31/19
Conditions of Approval (if any):	/ /