		OCD Artes	ia							
E SUNDRY	UNITED STATES EPARTMENT OF THE INTERJ SUREAU OF LAND MANAGEMEN NOTICES AND REPORTS O Is form for proposals to drill o ell. Use form 3160-3 (APD) for s	NT DEC 12 DN WELLS	2018	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM94830 6. If Indian, Allottee or Tribe Name						
SUBMIT IN	TRIPLICATE - Other instruction	ns on page 2		7. If Unit or CA/Agre	ement, Name and/or No.					
Type of Well     Gas Well     Gas Well     Gas Well     Operator     Name of Operator	Contact: TINA H		8. Well Name and No. CUADRITO AZO FEDERAL 1 9. API Well No.							
EOG Y RESOURCES, INC. 3a. Address 104 SOUTH FOURTH STRE ARTESIA, NM 88210		esources.com none No. (include area code) 575-748-4168	nclude area code) 10. Field and Pool or Exploratory							
4. Location of Well (Footage, Sec., Sec 31 T20S R23E NWNW 8				11. County or Parish, EDDY COUNTY						
12. CHECK THE A	PPROPRIATE BOX(ES) TO IN	DICATE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA					
TYPE OF SUBMISSION		ACTION								
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> </ul>	<ul> <li>Alter Casing</li> <li>Casing Repair</li> <li>Change Plans</li> </ul>	<ul> <li>Deepen</li> <li>Hydraulic Fracturing</li> <li>New Construction</li> <li>Plug and Abandon</li> <li>Plug Back</li> </ul>	☐ Reclama	lete arily Abandon	<ul> <li>Water Shut-Off</li> <li>Well Integrity</li> <li>Other</li> </ul>					
Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for This well has valuable up hole this well and recomplete in 20 If well fails MIT, contingency a MIT with the previously subm	e recompletion potential. Reques 19. Jan is to plug and abandon the w itted plug and abandonment NOI	d No. on file with BLM/BIA multiple completion or reco ther all requirements, includi ting approval to Tempo vell immediately followin and COA?s approved	. Required sub mpletion in a n ing reclamation rarily Aband ng a failed	sequent reports must be ew interval, a Form 316 , have been completed a	filed within 30 days 0-4 must be filed once					
1. MIRU all safety equipment 2. RIH with GR/JB to 4574 ft. 3. Set an RBP at 4524 ft. Loa 4. Conduct MIT and chart for 5. Cap wellhead with night ca	BLM and NMOCD. p and gauge.			E ATTACHE						
<ol> <li>I hereby certify that the foregoing is</li> <li>Name (Printed/Typed) TINA HUE</li> </ol>	Electronic Submission #445694 For EOG Y RESOUR		Information Carlsbad							
Signature (Electronic	Submission)	Date 11/29/20	Date 11/29/2018							
	THIS SPACE FOR FEI	DERAL OR STATE (	OFFICE US	E						
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equivily that the applicant holds legal or equivily describe according to accord	uitable title to those rights in the subject l				12-6-18 Date					
which would enfitle the applicant to condu- Title 18 U.S.C. Section 1001 and Title 43 States any fulse, fictitious or fraudulent		r any person knowingly and	willfully to mal	te to any department or a	agency of the United					
(Instructions on page 2) ** OPERA	TOR-SUBMITTED ** OPERA	TOR-SUBMITTED **	OPERAT	OR-SUBMITTED	**					

## Additional data for EC transaction #445694 that would not fit on the form

1

### 32. Additional remarks, continued

.

Wellbore schematics attached

• .

۲

Cuadrito	AZO F	ede	ral #1		11/29/20	18 - B	efore						
COMMENTS	1												-,
КВ: 25.3													
	i i				CASING DE	SIZE	WGHT	GRADE	THREAD	Тор	Bottom	SXS	
	! ···.				A	9 5/8	36	J-55	11111111111	0	1,410	1200	circulated
		ľ			B	5 1/2	17 8 15.5	J-55 & N-80		0	8,430	1600	circulated
												_	
					TOPS								
	÷.,				Glorieta	1,578							
					Abo Wolfcamp	3,598							
	1.	•			Cisco	4,692 5,880							
					Morrow	8,087							
	1				· · · · · · · · · · · · · · · · · · ·								
	1			:									
	A												
				1									
				l, j									
Wolfcamp Perfs 4574 - 4610													
Pens 4574 - 4610													
I Cmt. plug @ 4,664' - 4,890' (WC Top)		5				•							
		Ĩ	LULA CTINGSANA										
Cmt. plug @ 5,680' - 5,933' (Cisco Top)		2	er Lands Fr										
		3											
CIBP w/ 25 Sx Cemen 7943 - 8146 Perforations 8196 - 8224			14.11.11.12.15.144										
FEITOTBROIDS 0190 - 0224													
		_											
				L. I								· - · •	
		$\angle 2$	$\times$	$\square$									
۱ – ۱	Pata	8 7,840			L	Prepa	ared by: MJM			(	Dale: 29-N	ov-2018	
	0164 61												


.

-

•

•

.



•

٠

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822, Lea County 575-393-3612.

# 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.