***	••		

	UNITED STATE: EPARTMENT OF THE I SUREAU OF LAND MANA	NTERIOR	FEB 21	2019	OMB N Expires: J	APPROVED O. 1004-0137 anuary 31, 2018			
SUNDRY	NOTICES AND REPO	ESIA O.C.I	5. Lease Serial No. NMNM32636						
abandoned we	is form for proposals to ell. Use form 3160-3 (AP	D) for such	proposals.	Ando	6. If Indian, Allottee of	or Tribe Name			
SUBMIT IN	TRIPLICATE - Other ins	tructions on	page 2		7. If Unit or CA/Agre	ement, Name and/or No.			
1. Type of Well Gas Well Ot		8. Well Name and No. AMOCO 11 FED 6							
2. Name of Operator CHEVRON USA INCORPOR	Contact: ATED E-Mail: CHERREF	URILLO CHEVRON.CO							
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		3b. Phone N Ph: 575.20 Fx: 575.26		ode)	10. Field and Pool or E LOVING	 Field and Pool or Exploratory Area E LOVING 			
4. Location of Well (Footage, Sec., 7	T., R., M., or Survey Description)	11. County or 1			State			
Sec 11 T23S R28E NWNE 86	60FNL 1651FEL			EDDY COUNTY, NM					
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE	OF NOTI	CE, REPORT, OR OTH	IER DATA			
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION								
Notice of Intent	Acidize	Dee	epen	D Prod	duction (Start/Resume)	□ Water Shut-Off			
Subsequent Report	Alter Casing		Iraulic Fracturir		lamation	Well Integrity			
	Casing Repair	—	w Construction	—	omplete	🛛 Other ShutIn Notice			
Final Abandonment Notice	 Change Plans Convert to Injection 		g and Abandon g Back	-	nporarily Abandon ter Disposal				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. CHEVRON USA INC RESPECTFULLY REQUESTS FOR A SHUT IN STATUS ON THE ABOVE WELL THIS WAS NEWLY ACQUIRED FROM ROCKCLIFF OPERATING NEW MEXICO LLC EFFECTIVE NOVEMBER 1,2018. THIS WELL IS CURRENTLY SHUT IN AND NOT IN USE PENDING THE COMPLETE REPLACEMENT OF THE AMOCO FEDERAL 11 CENTRAL TANK BATTERY. WE EXPECT TO HAVE THE WELL TIED IN AND PRODUCING AGAIN BY APRIL 30,2019. AN ADDITIONAL FORM 3160-5 NOTICE TO RETURN WELL TO PRODUCTION WILL BE SUBMITTED TO BLM ONCE THE FACILITY REPLACEMENT IS COMPLETED AND WELL HAS STARTED BACK UP.									
IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT RON DEBRUIN/SR PRODUCTION ENGINEER AT 432-687-7311.									
SHUT IN TILL 4/2	olig Shuta	- appro	_		fil 4-30-2019	-ey_			
14. I hereby certify that the foregoing is	Erue and correct. Electronic Submission #4 For CHEVRON U Inmitted to AFMSS for proce	SA INCORPO	RATED, sent t	to the Carls	bad	0			
Name (Printed/Typed) CINDY H			Title PERMITTING SPECIALIST						
Signature (Electronic S	Submission)		Date 02/06/2019						
	THIS SPACE FO		L OR STAT	E OFFICE	USE				
Approved By /s/ Jonatl	hon Shepard	ſ	Petro	bleum	Engineer	FEB 1 4 2019			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivient would entitle the applicant to condu	d. Approval of this notice does hitable title to those rights in the		Carlsbad Field Office						
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a catatements or representations as	crime for any pe to any matter w	rson knowingly a ithin its jurisdiction	und willfully to on.	o make to any department or a	agency of the United			
(Instructions on page 2) ** BLM REVI	SED ** BLM REVISED	** BLM RE	EVISED ** BI	LM REVIS	ED ** BLM REVISED) **			