UNITED STATES CALLINGS FIELD OF DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Artesia SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						5. Lea NN	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC028784A 6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on page 2					 If Unit or CA/Agreement, Name and/or No. NMNM88525X Well Name and No. BURCH KEELY UNIT 84 						
1. Type of Well S Oil Well Gas Well Other											
2. Name of Operator Contact: SANDY BALLARD COG OPERATING LLC E-Mail: sballard@concho.com						9. API Well No. 30-015-03070-00-S1					
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701 3b. Phone N Ph: 432-6				o. (include area code) 86-4373				10. Field and Pool or Exploratory Area GRAYBURG			
Location of Well (Footage, Sec., 7		11. Co	11. County or Parish, State								
Sec 24 T17S R29E NWSW 1		EDDY COUNT									
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATU	RE OF	NOTICE	I E, REPO	RT, C	R OTHE	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION										
 Notice of Intent Subsequent Report Final Abandonment Notice 	 Acidize Alter Casing Casing Repair Change Plans Convert to Injection 	☐ Hyd ☐ New ☐ Plug	 Hydraulic Fracturing Recla New Construction Reco Plug and Abandon Temp 						 Water Shut-Off Well Integrity Other Venting and/or Flammed 		
following completion of the involved testing has been completed. Final Al determined that the site is ready for f Burch Keely Unit 84 Burch Keely Unit 23A Battery (Permit approval: Electronic S Actual gas flared for this batter Aug Total for Battery = 0 MCF Sept Total for Battery = 4100 MCF Oct Total for Battery = 4044 mcf Nov	bandonment Notices must be fil inal inspection. Submission #432038	led only after all 1	requirements DIIOWS :	, includir	eptec NM	on, have b	een co	mpleted and	t the operator has		
 I hereby certify that the foregoing is Con Name (Printed/Typed) SANDY E 	# Electronic Submission For COG C nmitted to AFMSS for proc	DPERATING L L	.C, sent to SCILLA PE	the Car REZ on	risbad	- 9 (19PP1	100SE	•			
·····							<u> </u>	STANT			
Signature (Electronic S	THIS SPACE FC			2/20/20					<u> </u>		
			LADOF	DIC		2-00	R	<u> </u>			
				باسات و		INLUU	עווי				
pproved By			Title						Date		
pproved By	uitable title to those rights in the		ll r	FEB	2 2 20	19	/s/	Jonat	Date		

** BLM REVISED **

••



Additional data for EC transaction #455354 that would not fit on the form

32. Additional remarks, continued

Total for Battery = 158 mcf

NUMBER OF WELLS TO FLARE: (31) BURCH-KEELY UNIT 84 30-015-03070 BURCH-KEELY UNIT 111 30-015-21294 BURCH-KEELY UNIT 112 30-015-03075 BURCH-KEELY UNIT 112 30-015-03087 BURCH-KEELY UNIT 132 30-015-03087 BURCH-KEELY UNIT 132 30-015-03087 BURCH-KEELY UNIT 132 30-015-03087 BURCH-KEELY UNIT 227 30-015-28687 BURCH-KEELY UNIT 227 30-015-28687 BURCH-KEELY UNIT 254 30-015-28585 BURCH-KEELY UNIT 266 30-015-28585 BURCH-KEELY UNIT 266 30-015-28585 BURCH-KEELY UNIT 278 30-015-28809 BURCH-KEELY UNIT 278 30-015-29511 BURCH-KEELY UNIT 281 30-015-30491 BURCH-KEELY UNIT 312 30-015-31434 BURCH-KEELY UNIT 312 30-015-31434 BURCH-KEELY UNIT 313 30-015-31526 BURCH-KEELY UNIT 314 30-015-31526 BURCH-KEELY UNIT 339 30-015-32700 BURCH-KEELY UNIT 378 30-015-35564 BURCH-KEELY UNIT 603 30-015-35564 BURCH-KEELY UNIT 603 30-015-38571 BURCH-KEELY UNIT 611 30-015-38646 BURCH-KEELY UNIT 613 30-015-40375 BURCH-KEELY UNIT 613 30-015-40375 BURCH-KEELY UNIT 613 30-015-40375 BURCH-KEELY UNIT 613 30-015-40383 BURCH-KEELY UNIT 613 30-015-40383 BURCH-KEELY UNIT 613 30-015-40383 BURCH-KEELY UNIT 613 30-015-40384 BURCH-KEELY UNIT 613 30-015-40385 BURCH-KEELY UNIT 603 30-015-40385 BURCH-KEELY UNIT 613 30-015-40386 BURCH-KEELY UNIT 613 30-015-40386

. ·

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT SHUT DOWN DUE TO HLP OR PLANT MAINTENANCE

۰.

. .